The following site is being submitted for inclusion into the GIS registry:

- For DNR County and Region list go to:
  g:\pf\pecfa\site\gis\BRRTS County and Region Codes.xls
- To begin, click on field to the right of *BRRTS ID (no dashes)*:.
- Use Tab, ↓ or Pg Down to navigate form. Print & include with file when completed.

This is a:	New Submittal
BRRTS ID (no dashes):	**0305000737**
Comm # (no dashes):	54303263369
County:	Brown
Region:	Northeast
Site name:	Tri-Star Service Center
Street Address:	1869 Shawano Ave
City:	Green Bay
Final Closure Date	2001-11-07
Closure Conditions:	met
Off-source property contamination?	No
(If yes, attach locational data and deed information on pg. 2)	
Right-of-way contamination?	Yes
Contaminated media:	Groundwater
GPS Coordinates (meters in the **WTM91** projection)	
Easting (X):	673119.000000000
Northing (Y):	452999.000000000
Collection Method:	
Scale or Resolution:	1:08,000
(1:24,000 scale or finer)	("**1:**" and comma is default)
Prepared by:	
Submitted by:	Cheryl Nelson

Source Property Checklist

- ☒ Final Closure Letter
- ☒ Copy of the most recent deed, which includes legal description for all properties w/ GW > NR 140 ES
- ☐ Where the legal description in the deed(s) refers to a certified survey map or recorded plat map, include those documents
- ☐ Parcel ID for all properties w/ GW > NR 140 ES
- ☒ General Location Map
- ☒ Detailed Location Map showing property boundaries, buildings, MW(s) and/or potable wells etc for properties with GW >NR140 ES
- ☒ Latest Map(s) showing extent or outline of current GW plume (isoconcentrations)
- ☒ Map showing GW flow direction
- ☒ Latest Table of GW results
- ☐ Geologic cross section (if generated as part of the site investigation)
- ☐ Statement signed by RP certifying correctness of legal descriptions
- ☐ Updated Database

ENVIRONMENTAL & REGULATORY SERVICES
DIVISION
BUREAU OF PECFA
P. O. Box 8044
Madison, Wisconsin 53708-8044
Fax #: (608) 267-1381
TDD #: (608) 264-8777
http://www.commerce.state.wi.us
http://www.wisconsin.gov
Scott McCallum, Governor
Philip Edw. Albert, Acting Secretary

Wisconsin
Department of Commerce

November 7, 2001

Mr. Donald Hanson
Tri-Star Service Center
1869 Shawano Avenue
Green Bay, WI 54303

Subject:: **Case Closure** – Tri-Star Service Center
1869 Shawano Avenue, Green Bay

COMMERCE #54303-2633-69 **DNR #03-05-000737**

Dear Mr. Hanson:

The above referenced site was reviewed for closure by Wisconsin Department of Commerce PECFA Site Review staff in response to the closure request prepared by your consultant, Envirogen. A conditional closure status was approved on January 6, 2001. Conditions of closure were the filing of a Soil and Groundwater Use Restriction, Notification of Right-Of-Way (ROW) contamination and the abandonment of all monitoring wells, piezometers and groundwater sumps. On October 31, 2001, Commerce received these conditions of closure. It is understood that groundwater-monitoring sumps 1-4 will remain in use to monitor existing UST bed. Using the standards established in NR 700, and the risk criteria of Comm 46, Commerce has determined that this site does not pose a significant threat to the environment and human health and no further investigation or remedial action is necessary.

IMPORTANT: If, in the future subsequent information indicates a need to reopen this case, any original claim under the PECFA fund would also reopen and you may apply for assistance to the extent of remaining eligibility.

If you have any questions, feel free to contact me at (608) 266-0593.

Sincerely,

Brian F. Taylor
Hydrogeologist
Department of Commerce
PECFA Site Review Section

cc: electronic storage
Mr. Mr. Matt Oberhofer, Envirogen

ERS-5524-E (R. 4/98)

1829925

Document Number

NOTICE OF CONTAMINATION TO PROPERTY

BROWN COUNTY
REGISTER OF DEEDS
CATHY WILLIQUETTE

2001 JUL 27 A 8:25

Legal Description of the Property: In re:

LOT ONE (1) OF A CERTIFIED SURVEY MAP RECORDED IN THE OFFICE OF THE REGISTER OF DEEDS FOR BROWN COUNTY, IN VOLUME 4 OF CERTIFIED SURVEY MAPS, PAGE 209, MAP NO. 1105, SAID MAP BEING PART OF PRIVATE CLAIM ONE (1) WEST SIDE OF FOX RIVER, IN THE CITY OF GREEN BAY, BROWN COUNTY, WISCONSIN, AS AMENDED BY AFFIDAVIT IN JACKET 4663 RECORDS, IMAGE 12, BROWN COUNTY RECORDS.

Recording Area

Name and Return Address
Dan Patton
1869 Shawano Avenue
Green Bay, WI 54303

1200 (2)

6-258-A-6
Parcel Identification Number (PIN)

STATE OF WISCONSIN)
) ss
COUNTY OF BROWN)

Section 1. Dan Patton is the owner of the above-described property.

Section 2. One or more petroleum discharges have occurred at this property contaminating groundwater above NR 140 enforcement standards and soils above NR 720 residual contaminant levels of the Wisconsin Administrative Code exist(s) on this property.

Section 3. It is the desire and intention of the property owner to impose restrictions on the property which will make it unnecessary to conduct additional soil or groundwater remediation activities on the property at the present time. The owner hereby declares that all of the property described above is held and shall be held, conveyed or encumbered, leased, rented, used, occupied and improved subject to the following limitations and/or restrictions:

Anyone who proposes to construct or reconstruct a well on this property is required to contact the Department of Natural Resources' Bureau of Drinking Water and Groundwater, or its successor agency, to determine what specific prohibitions or requirements are applicable, prior to constructing or reconstructing a well on this property. No well may be constructed or reconstructed on this property unless applicable requirements are met.

Also,

Residual petroleum contaminated soil and groundwater remains on this site. According to the report filed by Envirogen, Inc dated October 5, 1998, the residual contaminated soils and groundwater are located throughout the site with groundwater moving in a northeasterly direction. Therefore, an impermeable cap or cover (i.e. concrete, asphalt) shall be maintained across this property until: 1). The soil is actively remediated or removed or; 2). It can be shown that the soil has naturally degraded to levels shown to be protective of the environment and human health. If subsurface work is done in the contaminated areas, the contamination shall be

properly treated or disposed of in accordance with applicable laws. File references: PECFA Claim number 54303-2633-69 and BRRTS 03-05-000737, Envirogen, Inc, report dated October 5, 1998.

Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Commerce, or its successor, issue a determination that the restrictions set forth in this covenant are no longer required. That property owner shall provide any and all necessary information to the Department in order for the Department to be able to make a determination. Upon receipt of such a request, the Department shall determine whether or not the restrictions contained herein can be extinguished. Conditions under which a restriction may be extinguished will be determined in accordance with the site specific standards, rules and laws for this property. If the Department determines that the restrictions can be extinguished, an affidavit, with a copy of the Department's written determination, may be recorded to give notice that this restriction, or portions of this restriction are no longer binding. Any restriction placed upon this property shall not be extinguished without the Department's written determination.

IN WITNESS WHEREOF, the owner of the property has executed this document, this 26th day of July, 2001.

Signature: Dan Patton

Printed Name: Dan Patton

Title: N/A

Subscribed and sworn to before me
this 26th day of July, 2001

NOTARY

Mary A. Cowan
Notary Public, State of Wisconsin
My commission 4-18-04

This document was drafted by the Wisconsin Department of Commerce.



SCALE
1:24000

1/2 0 1 MILE

1000 0 1000 2000 3000 4000 5000 6000 7000 FEET

1 .5 0 1 KILOMETER

CONTOUR INTERVAL 10 FEET

N

LOCATION

THE INTERPRETATIONS IN THIS FIGURE ARE BASED ON KNOWN POINTS IN TIME AND SPACE AND ARE INTEGRAL TO A WRITTEN REPORT AND SHOULD BE REVIEWED IN THAT CONTEXT.

Fluid Management, Inc.

FIGURE 2.1
SITE LOCATION MAP
TRI-STAR SERVICE
GREEN BAY, WISCONSIN

DRAWING NO.	DRAWN BY:	DLA	CHECKED BY:	VLR	APPROVED BY:	SOC
94.329W21		11/30/94		12/1/94		12/16/94



LEGEND

- APPROXIMATE PROPERTY BOUNDARY
- CYCLONE FENCE
- OE — OVERHEAD ELECTRIC
- SUMP
- MONITORING WELL
- PIEZOMETER
- ( ) DISSOLVED OXYGEN CONCENTRATION IN mg/L
- (NA) NOT ANALYZED
- 2 ISOCONCENTRATION CONTOUR

TANK LEGEND:

- A 6,000-GALLON UNLEADED GASOLINE UST
- B 6,000-GALLON UNLEADED GASOLINE UST
- C 12,000-GALLON PREMIUM UNLEADED GASOLINE UST

NOTE: FORMER USTs WERE IN THE SAME LOCATION AS THE EXISTING USTs.

Fluid Management
A Division of ENVIROGEN, Inc.

SCALE
0 10' 20' 30' 40'

N

Dissolved Oxygen Distribution (5/12/98)
Tri Star Service Site
Green Bay, Wisconsin

FIGURE NO. 9

THE INTERPRETATIONS IN THIS FIGURE ARE BASED ON KNOWN POINTS IN TIME AND SPACE AND ARE INTEGRAL TO A WRITTEN REPORT AND SHOULD BE REVIEWED IN THAT CONTEXT.

DRAWING NO.	DRAWN BY:	CHECKED BY:	APPROVED BY:
94.239L9	RRT 9/29/98		



LEGEND

- APPROXIMATE PROPERTY BOUNDARY
- CYCLONE FENCE
- OE — OVERHEAD ELECTRIC
- SUMP
- MONITORING WELL
- PIEZOMETER
- ( ) GROUNDWATER ELEVATION IN FEET ABOVE MSL
- (NA) NOT ANALYZED
- 610 EQUIPOTENTIAL CONTOUR

TANK LEGEND:

- A 6,000-GALLON UNLEADED GASOLINE UST
- B 6,000-GALLON UNLEADED GASOLINE UST
- C 12,000-GALLON PREMIUM UNLEADED GASOLINE UST

NOTE: FORMER USTs WERE IN THE SAME LOCATION AS THE EXISTING USTs.

PIEZOMETER ELEVATIONS ARE SHOWN BUT WERE NOT USED TO GENERATE POTENTIOMETRIC SURFACE.

HYDRAULIC GRADIENT (dh/dl) = 0.017 ft/ft

Fluid Management
A Division of ENVIROGEN, Inc.

SCALE
0 10' 20' 30' 40'

N

Potentiometric Surface (5/12/98)
Tri Star Service Site
Green Bay, Wisconsin

FIGURE NO.
7

THE INTERPRETATIONS IN THIS FIGURE ARE BASED ON KNOWN POINTS IN TIME AND SPACE AND ARE INTEGRAL TO A WRITTEN REPORT AND SHOULD BE REVIEWED IN THAT CONTEXT.

DRAWING NO.	DRAWN BY:	CHECKED BY:	APPROVED BY:
94.239L7	RRT 9/29/98	ASL 10/5/98	MMV 10/5/98

TABLE 2

Historical Groundwater Laboratory Analytical Results

Tri-Star Service Site

Green Bay, Wisconsin

Monitoring Well	Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	Naphthalene
MW-1	06/19/95	**18,000**	**3,000**	**35,000**	**15,000**	**1,300**	**700**
	08/15/95	**20,000**	**2,900**	**33,000**	**16,000**	**1,000**	NA
	09/18/95	**15,000**	**2,200**	**27,000**	**12,000**	<600	NA
	8/19/96	NA	NA	NA	NA	NA	NA
	12/19/96	NA	NA	NA	NA	NA	NA
	2/28/97	NA	NA	NA	NA	NA	NA
	05/09/97	NA	NA	NA	NA	NA	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	NA	NA	NA	NA	NA	NA
MW-2	06/19/95	**110**	**24**	**1.7**	**22**	**130**	**3.1**
	08/15/95	**260**	**4.5**	<1.0	**4**	**700**	NA
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	<0.5	<1.0	<1.0	<3.0	~~17~~ 17	NA
	12/19/96	<0.50	<1.0	<1.0	<3.0	~~23~~ 23	NA
	2/28/97	<0.13	<0.22	**0.23**	<0.23	~~37~~ 37	NA
	05/09/97	**0.43**	**3.7**	**0.77**	**2.6**	~~15~~ 15	NA
	1/16/98	**7.7**	**0.36**	**0.51**	<0.56	~~45~~ 45	NA
	05/12/98	<0.10	**1.8**	<0.10	**0.51**	**7.3**	**0.35**
NR 140 Enforcement Standard		5.0	700	343	620	60	40
NR 140 Preventive Action Limit		0.5	140	68.6	124	12	8

Notes: All results are reported in ppb

(Continued)

Shading indicates value equals or exceeds the NR 140 enforcement standard

Cross hatching indicates value equals or exceeds the NR 140 preventive action limit

MTBE: Methyl t-butyl ether

NA: Not analyzed

Checked by: _____ Approved by: _____

TABLE 2 (Continued)
Historical Groundwater Laboratory Analytical Results
Tri-Star Service Site
Green Bay, Wisconsin

Monitoring Well	Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	Naphthalene
MW-3	06/19/95	<1.0	<1.0	<1.0	<3.0	<1.0	<1.0
	08/15/95	<1.0	<1.0	<1.0	<3.0	<1.0	NA
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	<0.50	<1.0	<1.0	<3.0	**2**	NA
	12/19/96	<0.50	<1.0	<1.0	<3.0	<1.0	NA
	2/28/97	NA	NA	NA	NA	NA	NA
	05/09/97	NA	NA	NA	NA	NA	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	<0.10	<0.25	<0.10	<0.25	**0.98**	**0.31**
MW-4	06/19/95	<1.0	<1.0	<1.0	<3.0	<1.0	<1.0
	08/15/95	<1.0	<1.0	<1.0	<3.0	<1.0	NA
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	<0.50	<1.0	<1.0	<3.0	<1.0	NA
	12/19/96	<0.50	<1.0	<1.0	<3.0	<1.0	NA
	2/28/97	NA	NA	NA	NA	NA	NA
	05/09/97	NA	NA	NA	NA	NA	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	<0.10	<0.25	<0.10	<0.25	<0.25	<0.10
NR 140 Enforcement Standard		5.0	700	343	620	60	40
NR 140 Preventive Action Limit		0.5	140	68.6	124	12	8

(Continued)

Notes: All results are reported in ppb.
MTBE: Methyl t-butyl ether
NA: Not analyzed

Checked by: _____
Approved by: _____

TABLE 2 (Continued)
Historical Groundwater Laboratory Analytical Results
Tri-Star Service Site
Green Bay, Wisconsin

Monitoring Well	Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	Naphthalene
MW-5	06/19/95	17	<1.0	<1.0	<3.0	<1.0	<1.0
	08/15/95	<1.0	<1.0	<1.0	<3.0	<1.0	NA
	9/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	<0.50	<1.0	<1.0	<3.0	<2.0	NA
	12/19/96	<0.50	<1.0	<1.0	<3.0	<1.0	NA
	2/28/97	<0.13	<0.22	<0.20	<0.23	<0.16	NA
	05/09/97	<0.21	<0.21	<0.48	<0.56	**0.33**	NA
	1/16/98	<0.21	<0.21	<0.48	<0.56	**0.66**	NA
	05/12/98	<0.10	<0.25	<0.10	<0.25	**0.66**	**0.24**
MW-6	06/19/95	<1.0	<1.0	<1.0	<3.0	<1.0	<1.0
	08/15/95	<1.0	<1.0	<1.0	<3.0	<1.0	NA
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	<0.5	<1.0	<1.0	<3.0	<1.0	NA
	12/19/96	<0.5	<1.0	<1.0	<3.0	<1.0	NA
	2/28/97	NA	NA	NA	NA	NA	NA
	05/09/97	NA	NA	NA	NA	NA	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	<0.10	<0.25	<0.10	<0.25	<0.25	<0.10
NR 140 Enforcement Standard		5.0	700	343	620	60	40
NR 140 Preventive Action Limit		0.5	140	68.6	124	12	8

(Continued)

Notes: All results are reported in ppb.

Shading indicates value equals or exceeds the NR 140 enforcement standard

MTBE: Methyl t-butyl ether

NA: Not analyzed

Checked by: _____

Approved by: _____

TABLE 2 (Continued)
Historical Groundwater Laboratory Analytical Results
Tri-Star Service Site
Green Bay, Wisconsin

Monitoring Well	Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	Naphthalene
MW-7	06/19/95	<1.0	<1.0	<1.0	<3.0	<1.0	<1.0
	08/15/95	<1.0	<1.0	<1.0	<3.0	<1.0	NA
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	<0.5	<1.0	<1.0	<3.0	<1.0	NA
	12/19/96	<0.50	<1.0	<1.0	<3.0	<1.0	NA
	2/28/97	<0.13	<0.22	<0.20	<0.23	<0.16	NA
	05/09/97	<0.21	<0.21	<0.48	<0.56	<0.21	NA
	1/16/98	<0.21	<0.21	<0.48	<0.56	<0.21	NA
	05/12/98	<0.10	<0.25	<0.10	<0.25	<0.25	<0.10
MW-8	06/19/95	<1.0	<1.0	<1.0	<3.0	<1.0	<1.0
	08/15/95	<1.0	<1.0	<1.0	<3.0	<1.0	NA
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	<0.5	<1.0	<1.0	<3.0	<1.0	NA
	12/19/96	<0.50	<1.0	<1.0	<3.0	<1.0	NA
	2/28/97	NA	NA	NA	NA	NA	NA
	05/09/97	NA	NA	NA	NA	NA	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	<0.10	<0.25	<0.10	<0.25	<0.25	<0.10
NR 140 Enforcement Standard		5.0	700	343	620	60	40
NR 140 Preventive Action Limit		0.5	140	68.6	124	12	8

(Continued)

Notes: All results are reported in ppb.
MTBE: Methyl t-butyl ether
NA: Not analyzed

Checked by: _____
Approved by: _____

TABLE 2 (Continued)
Historical Groundwater Laboratory Analytical Results
Tri-Star Service Site
Green Bay, Wisconsin

Monitoring Well	Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	Naphthalene
MW-9	06/19/95	NA	NA	NA	NA	NA	NA
	08/15/95	<1.0	<1.0	<1.0	<3.0	<1.0	<1.0
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	<0.50	<1.0	<1.0	<3.0	<1.0	NA
	12/19/96	<0.50	<1.0	<1.0	<3.0	<1.0	NA
	2/28/97	NA	NA	NA	NA	NA	NA
	05/09/97	NA	NA	NA	NA	NA	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	<0.10	<0.25	<0.10	<0.25	<0.25	<0.10
MW-10	06/19/95	NA	NA	NA	NA	NA	NA
	08/15/95	<1.0	<1.0	<1.0	<3.0	<1.0	<1.0
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	<0.5	<1.0	<1.0	<3.0	<1.0	NA
	12/19/96	<0.50	<1.0	<1.0	<3.0	<1.0	NA
	2/28/97	NA	NA	NA	NA	NA	NA
	05/09/97	NA	NA	NA	NA	NA	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	<0.10	<0.25	<0.10	<0.25	<0.25	<0.10
NR 140 Enforcement Standard		5.0	700	343	620	60	40
NR 140 Preventive Action Limit		0.5	140	68.6	124	12	8

(Continued)

Notes: All results are reported in ppb.
MTBE: Methyl t-butyl ether
NA: Not analyzed

Checked by: _____
Approved by: _____

TABLE 2 (Continued)
Historical Groundwater Laboratory Analytical Results
Tri-Star Service Site
Green Bay, Wisconsin

Monitoring Well	Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	Naphthalene
MW-11	06/19/95	NA	NA	NA	NA	NA	NA
	08/15/95	650	960	130	930	<20	130
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	NA	NA	NA	NA	NA	NA
	12/19/96	NA	NA	NA	NA	NA	NA
	2/28/97	NA	NA	NA	NA	NA	NA
	05/09/97	NA	NA	NA	NA	NA	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	NA	NA	NA	NA	NA	NA
MW-20	1/16/98	24,000	2,900	24,000	12,600	530	530
	5/12/98	20,000	2,800	22,000	13,000	240	380
	4/14/99	17,000	3,300	16,000	15,500	290	470
	8/30/99	19,000	2,300	12,000	10,100	320	440
	3/24/00	17,400	2,130	11,000	9,670	474	1,340
	9/30/00	16,700	2,550	11,000	11,000	242	<2000
MW-21	1/18/98	8,700	3,500	11,000	13,400	650	570
	5/12/98	5,700	3,300	4,500	13,000	580	420
	4/14/99	3,500	2,900	1,900	10,200	750	680
	8/30/99	4,900	3,100	1,400	7,670	820	770
	3/24/00	6,420	3,550	571	8,750	759	770
	9/30/00	6,200	2,780	619	7,410	326	<800
NR 140 Enforcement Standard		5.0	700	343	620	60	40
NR 140 Preventive Action Limit		0.5	140	68.6	124	12	8

(Continued)

Notes: All results are reported in ppb

Shading indicates value equals or exceeds the NR 140 enforcement standard

Cross hatching indicates value equals or exceeds the NR 140 preventive action limit

MTBE: Methyl t-butyl ether

NA: Not analyzed

Checked by: _____

Approved by: _____

TABLE 2 (Continued)
Historical Groundwater Laboratory Analytical Results
Tri-Star Service Site
Green Bay, Wisconsin

Monitoring Well	Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	Naphthalene
PZ-1	06/19/95	78	<1.0	<1.0	<3.0	200	<1.0
	08/15/95	31	2.4	<2.0	<6.0	84	<2.0
	09/18/95	15	1.8	<1.0	<3.0	~~37~~ 37	NA
	8/19/96	NA	NA	NA	NA	NA	NA
	12/19/96	NA	NA	NA	NA	NA	NA
	2/28/97	NA	NA	NA	NA	NA	NA
	05/09/97	NA	NA	NA	NA	NA	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	NA	NA	NA	NA	NA	NA
PZ-2	06/19/95	NA	NA	NA	NA	NA	NA
	08/15/95	3,200	2,700	15,000	17,000	<1,000	<1,000
	09/18/95	750	<100	3,400	7,800	<400	NA
	8/19/96	NA	NA	NA	NA	NA	NA
	12/19/96	NA	NA	NA	NA	NA	NA
	2/28/97	NA	NA	NA	NA	NA	NA
	05/09/97	NA	NA	NA	NA	NA	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	NA	NA	NA	NA	NA	NA
NR 140 Enforcement Standard		5.0	700	343	620	60	40
NR 140 Preventive Action Limit		0.5	140	68.6	124	12	8

(Continued)

Notes: All results are reported in ppb.

Shading indicates value equals or exceeds the NR 140 enforcement standard

MTBE: Methyl t-butyl ether

NA: Not analyzed

Checked by: _____

Approved by: _____

TABLE 2 (Continued)
Historical Groundwater Laboratory Analytical Results
Tri-Star Service Site
Green Bay, Wisconsin

Monitoring Well	Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	Naphthalene
PZ-3	06/19/95	NA	NA	NA	NA	NA	NA
	08/15/95	<1.0	<1.0	<1.0	<3.0	<1.0	<1.0
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	<0.50	<1.0	<1.0	<3.0	<1.0	NA
	12/19/96	<0.50	<1.0	<1.0	<3.0	<1.0	NA
	2/28/97	<0.13	<0.22	<0.20	<0.23	<0.16	NA
	05/09/97	<0.21	<0.21	<0.48	<0.56	<0.21	NA
	1/16/98	<0.21	<0.21	<0.48	<0.56	<0.21	NA
	05/12/98	<0.10	<0.25	<0.10	<0.25	**1.2**	**0.22**
PZ-4	06/19/95	NA	NA	NA	NA	NA	NA
	08/15/95	**16**	<5.0	<5.0	<15	**440**	<5.0
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	<0.5	<1.0	<1.0	<3.0	**68**	NA
	12/19/96	<0.50	<1.0	<1.0	<3.0	**50**	NA
	2/28/97	<0.13	<0.22	**0.23**	<0.23	**8.9**	NA
	05/09/97	<0.21	<0.21	<0.48	<0.56	**30**	NA
	1/16/98	<0.21	<0.21	<0.48	<0.56	**25**	NA
	05/12/98	<0.10	<0.25	<0.10	<0.25	**17**	**0.23**
NR 140 Enforcement Standard		5.0	700	343	620	60	40
NR 140 Preventive Action Limit		0.5	140	68.6	124	12	8

(Continued)

Notes: All results are reported in ppb.

Shading indicates value equals or exceeds the NR 140 enforcement standard

Cross hatching indicates value equals or exceeds the NR 140 preventive action limit

MTBE: Methyl t-butyl ether

NA: Not analyzed

Checked by: _____

Approved by: _____

TABLE 2 (Continued)
Historical Groundwater Laboratory Analytical Results
Tri-Star Service Site
Green Bay, Wisconsin

Monitoring Well	Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	Naphthalene
PZ-5	06/19/95	NA	NA	NA	NA	NA	NA
	08/15/95	NA	NA	NA	NA	NA	NA
	09/18/95	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0
	8/19/96	NA	NA	NA	NA	NA	NA
	12/19/96	NA	NA	NA	NA	NA	NA
	2/28/97	NA	NA	NA	NA	NA	NA
	05/09/97	NA	NA	NA	NA	NA	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	NA	NA	NA	NA	NA	NA
SUMP-1	06/19/95	NA	NA	NA	NA	NA	NA
	08/15/95	NA	NA	NA	NA	NA	NA
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	**530**	**12**	~~190~~ 190	**29**	**2,200**	NA
	12/19/96	**210**	**33**	**1.9**	**6.8**	**630**	NA
	2/28/97	NA	NA	NA	NA	NA	NA
	05/09/97	**23**	**0.27**	<0.48	<0.56	**64**	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	NA	NA	NA	NA	NA	NA
NR 140 Enforcement Standard		5.0	700	343	620	60	40
NR 140 Preventive Action Limit		0.5	140	68.6	124	12	8

(Continued)

Notes: All results are reported in ppb.

Shading indicates value equals or exceeds the NR 140 enforcement standard

Cross hatching indicates value equals or exceeds the NR 140 preventive action limit

MTBE: Methyl t-butyl ether

NA: Not analyzed

Checked by: _____

Approved by: _____

TABLE 2 (Continued)

Historical Groundwater Laboratory Analytical Results

Tri-Star Service Site

Green Bay, Wisconsin

Monitoring Well	Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	Naphthalene
SUMP-2	06/19/95	NA	NA	NA	NA	NA	NA
	08/15/95	NA	NA	NA	NA	NA	NA
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	11,000	860	22,000	4,500	12,000	NA
	12/19/96	320	370	370 11 180	180	490	NA
	2/28/97	200	380	380 8.3 360	360	260	NA
	05/09/97	320	370	370 11 180	180	490	NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	NA	NA	NA	NA	NA	NA
SUMP-3	06/19/95	NA	NA	NA	NA	NA	NA
	08/15/95	NA	NA	NA	NA	NA	NA
	09/18/95	NA	NA	NA	NA	NA	NA
	8/19/96	200	3.6	19	29	850	NA
	12/19/96	49	3.0	<1.0	<3.0	610	NA
	2/28/97	24	0.31	0.27	0.33	280	NA
	05/09/97	5	<0.21	<0.48	<0.56	49	49 NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	NA	NA	NA	NA	NA	NA
NR 140 Enforcement Standard		5.0	700	343	620	60	40
NR 140 Preventive Action Limit		0.5	140	68.6	124	12	8

(Continued)

Notes: All results are reported in ppb.

Shading indicates value equals or exceeds the NR 140 enforcement standard

Cross hatching indicates value equals or exceeds the NR 140 preventive action limit

MTBE: Methyl t-butyl ether

NA: Not analyzed

Checked by: _____

Approved by: _____

TABLE 2 (Continued)
Historical Groundwater Laboratory Analytical Results
Tri-Star Service Site
Green Bay, Wisconsin

Monitoring Well	Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	Naphthalene
SUMP-4	06/19/95	NA	NA	NA	NA	NA	NA
	08/15/95	NA	NA	NA	NA	NA	NA
	9/18/95	NA	NA 170	NA 190	NA	NA	NA 9.5
	8/19/96	340	170	190	1,200	570	9.5
	12/19/96	180	100	7.8	25	350	NA
	2/28/97	100	44	2	12	200	NA
	05/09/97	21	43	5.8	46	49	49 NA
	1/16/98	NA	NA	NA	NA	NA	NA
	05/12/98	NA	NA	NA	NA	NA	NA
SUMP-5	06/19/95	NA	NA	NA	NA	NA	NA
	08/15/95	NA	NA	NA	NA	NA	NA
	09/18/95	NA	NA 260	NA	NA	NA	NA
	8/19/96	3,000	260	4,800	4,500	3,000	NA
	12/19/96	1,900	280	280 18 310	310	930	NA
	2/28/97	1,300	300	300 21 190	190	770	NA
	05/09/97	150	12	4.5	25	240	NA
	1/16/98	170	120	120 25	43	230	NA
	05/12/98	48	24	0.83	4.0	74	1.4
NR 140 Enforcement Standard		5.0	700	343	620	60	40
NR 140 Preventive Action Limit		0.5	140	68.6	124	12	8

Notes: All results are reported in ppb.

Shading indicates value equals or exceeds the NR 140 enforcement standard

XX Cross hatching indicates value equals or exceeds the NR 140 preventive action limit

MTBE: Methyl t-butyl ether

NA: Not analyzed

Checked by: _____

Approved by: _____