

GIS REGISTRY INFORMATION

SITE NAME:	Canterbury Farm & Greenhouses			FID #	
BRRTS #:	03-05-307271			(if appropriate):	
COMMERCE # (if appropriate):	54313-7317-14				
CLOSURE DATE:	7/12/05				
STREET ADDRESS:	614 Fredrick Ct				
CITY:	Green Bay				
SOURCE PROPERTY GPS COORDINATES (meters in WTM91 projection):				X =	669172
				Y =	455590
CONTAMINATED MEDIA:	Groundwater	<input type="checkbox"/>	Soil	<input type="checkbox"/>	Both
					<input checked="" type="checkbox"/>
OFF-SOURCE GW CONTAMINATION >ES:		Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
• IF YES, STREET ADDRESS:					
• GPS COORDINATES (meters in WTM91 projection):					
		X =		Y =	
OFF-SOURCE SOIL CONTAMINATION >Generic or Site-Specific RCL (SSRCL):		Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
• IF YES, STREET ADDRESS 1:					
• GPS COORDINATES (meters in WTM91 projection):					
		X =		Y =	
CONTAMINATION IN RIGHT OF WAY:		Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
<u>DOCUMENTS NEEDED</u>					
Closure Letter, and any conditional closure letter issued					<input checked="" type="checkbox"/>
Copy of most recent deed, including legal description, for all affected properties					<input checked="" type="checkbox"/>
Certified survey map or relevant portion of the recorded plat map (if referenced in the legal description) for all affected properties					<input checked="" type="checkbox"/>
County Parcel ID number, if used for county, for all affected propertiesxVH-507					<input checked="" type="checkbox"/>
Location Map which outlines all properties within contaminated site boundaries on USGS topographic map or plat map in sufficient detail to permit the parcels to be located easily (8.5x14" if paper copy). If groundwater standards are exceeded, the map must also include the location of all municipal and potable wells within 1200' of the site.					<input checked="" type="checkbox"/>
Detailed Site Map(s) for all affected properties, showing buildings, roads, property boundaries, contaminant sources, utility lines, monitoring wells and potable wells. (8.5x14", if paper copy) This map shall also show the location of all contaminated public streets, highway and railroad rights-of-way in relation to the source property and in relation to the boundaries of groundwater contamination exceeding ch. NR 140 ESs and soil contamination exceeding ch. NR 720 generic or SSRCLs.					<input checked="" type="checkbox"/>
Tables of Latest Groundwater Analytical Results (no shading or cross-hatching)					<input checked="" type="checkbox"/>
Tables of Latest Soil Analytical Results (no shading or cross-hatching)					<input checked="" type="checkbox"/>
Isoconcentration map(s), if required for site investigation (SI) (8.5x14" if paper copy). The isoconcentration map should have flow direction and extent of groundwater contamination defined. If not available, include the latest extent of contaminant plume map.					<input checked="" type="checkbox"/>
GW: Table of water level elevations, with sampling dates, and free product noted if present See groundwater analytical table					<input checked="" type="checkbox"/>
GW: Latest groundwater flow direction/monitoring well location map (should be 2 maps if maximum variation in flow direction is greater than 20 degrees)					<input checked="" type="checkbox"/>
SOIL: Latest horizontal extent of contamination exceeding generic or SSRCLs, with one contour					<input checked="" type="checkbox"/>
Geologic cross-sections, if required for SI. (8.5x14' if paper copy)					<input checked="" type="checkbox"/>
RP certified statement that legal descriptions are complete and accurate.					<input checked="" type="checkbox"/>
Copies of off-source notification letters (if applicable) Notification letter to the present site owner – different from RP					<input checked="" type="checkbox"/>
Letter informing ROW owner of residual contamination (if applicable)(public, highway or railroad ROW)					<input checked="" type="checkbox"/>
Copy of (soil or land use) deed restriction (s) or deed notice if any required as a condition of closure					<input type="checkbox"/> na



commerce.wi.gov

ENVIRONMENTAL & REGULATORY SERVICES DIVISION
BUREAU OF PECFA
2129 Jackson Street
Oshkosh, Wisconsin 54901-1805
TDD #: (608) 264-8777
Fax #: (920) 424-0217
Jim Doyle, Governor
Mary P. Burke, Secretary

July 12, 2005

Mr. Harold W. Thompson
2867 Drake Place
Green Bay, WI 54313

RE: **Final Closure**

Commerce # 54313-7317-14 **WDNR BRRTS # 03-05-307271**
Canterbury Farm & Greenhouses, 614 Fredrick Court, Green Bay

Dear Mr. Thompson:

The Wisconsin Department of Commerce (Commerce) has received the items required as the condition for closure of the site referenced above. This case is now listed as "closed" on the Commerce database and will be included on the Wisconsin Department of Natural Resources (WDNR) Geographic Information System (GIS) Registry of Closed Remediation Sites to address residual soil and groundwater contamination. It is in your best interest to keep all documentation related to the environmental activities that were conducted.

If residual contamination is encountered in the future, it must be managed in accordance with all applicable state and federal regulations. If it is determined that any remaining contamination poses a threat, the case may be reopened and further investigation or remediation may be required.

Thank you for your efforts to bring this case to closure. If you have any questions, please contact me in writing at the letterhead address or by telephone at (920) 424-0046.

Sincerely,

A handwritten signature in black ink, appearing to read "Robert H. Klauk".

Robert H. Klauk
Hydrogeologist
Site Review Section

cc: Kurt A. Rasmussen - Endeavor Environmental Services, Inc.
Case File



commerce.wi.gov

ENVIRONMENTAL & REGULATORY SERVICES DIVISION
BUREAU OF PECFA
2129 Jackson Street
Oshkosh, Wisconsin 54901-1805
TDD #: (608) 264-8777
Fax #: (920) 424-0217
Jim Doyle, Governor
Mary P. Burke, Secretary

May 13, 2005

Mr. Harold W. Thompson
2867 Drake Place
Green Bay, WI 54313

RE: **Conditional Case Closure**

Commerce # 54313-7317-14 **WDNR BRRTS # 03-05-307271**
Canterbury Farm & Greenhouses, 614 Fredrick Court, Green Bay

Dear Mr. Thompson:

The Wisconsin Department of Commerce (Commerce) has reviewed the request for case closure, prepared by Endeavor Environmental Services, Inc., for the site referenced above. It is understood that residual soil and groundwater contamination remain on-site. Commerce has determined that this site does not pose a significant threat to the environment and human health. No further investigation or remedial action is necessary.

The following condition must be satisfied to obtain final closure:

- Documentation of the abandonment (WDNR Abandonment Form 3300-5B) of groundwater monitoring wells MW-1R, MW-2 through MW-5, MW-10, MW-11 and piezometer PZ-1.

This letter serves as your written notice of "no further action." Timely filing of your final PECFA claim is encouraged. If your claim is not received within 120 days of the date of this letter, interest costs incurred after 60 days of the date of this letter will not be eligible for PECFA reimbursement.

Thank you for your efforts to protect Wisconsin's environment. If you have any questions, please contact me in writing at the letterhead address or by telephone at (920) 424-0046.

Sincerely,

A handwritten signature in black ink, appearing to read "Robert H. Klauk". The signature is fluid and cursive, written over a white background.

Robert H. Klauk
Hydrogeologist
Site Review Section

cc: Joseph M. Ramcheck - Endeavor Environmental Services, Inc.
Case File

1945058

STATE BAR OF WISCONSIN FORM 1 - 1999
WARRANTY DEED

Document Number

BROWN COUNTY
REGISTER OF DEEDS
CATHY WILLIQUETTE

2002 OCT. 29 P 2:43

This Deed, made between **HAROLD W. THOMPSON** (a single person) and **RANDALL B. PIERRET** (a single person)

Grantor, and **TAAD Lawn Care, LLC**, a Wisconsin limited liability company,

Grantee.

Grantor, for a valuable consideration, conveys to Grantee the following described real estate in **Brown** County, State of Wisconsin (if more space is needed, please attach addendum):

Parts of Section 18, Township 24 North, Range 20 East, in the Village of Howard, Brown County, Wisconsin, described on addendum attached hereto and made a part hereof by reference.

Recording Area

Name and Return Address

TAAD Lawn Care, LLC
614 Frederic Court
Green Bay WI 54313

BAY TITLE

TI 53637

130

TRANSFER
1200.00
FEE

Together with all appurtenant rights, title and interests.

Grantor warrants that the title to the Property is good, indefeasible in fee simple and free and clear of encumbrances except highway rights of way and easements and restrictions of record.

VH-507

Parcel Identification Number (PIN)

This is (in part) homestead property.

(is) (is not)

Dated this 8th day of October, 2002.

Harold W. Thompson
Harold W. Thompson

* Randall B. Pierret

AUTHENTICATION

Signature(s) _____

authenticated this _____ day of _____,

ACKNOWLEDGMENT


STATE OF WISCONSIN)
) ss.

Brown County)

Personally came before me this 8th day of October, 2002 the above named Harold W. Thompson and Randall B. Pierret

TITLE: MEMBER STATE BAR OF WISCONSIN
(If not, _____
authorized by § 706.06, Wis. Stats.)

THIS INSTRUMENT WAS DRAFTED BY
Bernard U. Roels, Attorney



to me known to be the person(s) who executed the foregoing instrument and acknowledged the same.

Justin D. May
Justin D. May, Notary Public, State of Wisconsin

My Commission is permanent. (If not, state expiration date: _____)

(Signatures may be authenticated or acknowledged. Both are not necessary.)

1-22-06

* Names of persons signing in any capacity must be typed or printed below their signature.

Information Professionals Company, Fond du Lac, WI
800-655-2021

WARRANTY DEED

STATE BAR OF WISCONSIN
FORM No. 1 - 1999

1945058

ADDENDUM TO WARRANTY DEED

GRANTOR: Harold W. Thompson and Randall B. Pierret
GRANTEE: TAAD Lawn Care, LLC

Description of property conveyed:

Part of Government Lots Two (2) and Three (3), Section Eighteen (18), Township Twenty-four (24) North, Range Twenty (20) East, in the Village of Howard, Brown County, Wisconsin, described as follows:

Commencing at the northwesterly corner of Government Lot 2 of the said Section 18; thence South 16 deg. 23 min. 39 sec. West 1249.07 feet to a point on the easterly right-of-way line of Frederic Court, said point being the point of beginning; thence south 65 deg. 05 min. 20 sec. East along the southwesterly line of Lot 1 Vol. 3 Certified Survey Maps Page 523, 854.82 feet; thence South 1 deg. 14 min. 40 sec. West along the extension of the easterly line of the said Lot 1, Vol 3. Certified Survey Maps, Page 523, 426.23 feet to the northeasterly right-of-way line of S.T.H. "29-32"; thence North 65 deg. 39 min. 10 sec. West along the said northeasterly right-of-way line 412.56 feet to the southwesterly line of Government Lot 2 of the said Section 18; thence North 59 deg. 12 min. 49 sec. West along the said southwesterly line and along the southwesterly line of Government Lot 3 of the said Section 18 a distance of 531.99 feet; thence North 12 deg. 02 min. 37 sec. East 245.10 feet to the easterly right-of-way line of Frederic Court; thence along the said easterly line along a curve concave westerly, chord North 12 deg. 04 min. 11.5 sec. East 61.40 feet, radius 65.00 feet, central angle 56 deg. 21 min. 57 sec. 63.95 feet; thence continuing along the said easterly right-of-way line along a tangential curve concave easterly, chord North 3 deg. 44 min. 40 sec. East 44.16 feet, radius 65.00 feet, central angle 39 deg. 42 min. 54 sec. 45.06 feet to the point of beginning, subject to the easement recorded in Vol. 956 Records, Page 622.

AND;


Part of Government Lot Three (3), Section Eighteen (18), Township Twenty-four (24) North, Range Twenty (20) East, in the Village of Howard, Brown County, Wisconsin described as follows:

Commencing at the northwesterly corner of Government Lot 2 of the said Section 18; thence South 16 deg. 23 min. 39 sec. West 1249.07 feet to the easterly right-of-way line of Frederic Court; thence along the said easterly right-of-way line along a curve concave easterly, chord South 3 deg. 44 min. 40 sec. West 44.16 feet, radius 65.00 feet, central angle 39 deg. 42 min. 54 sec. 45.06 feet; thence continuing along the said easterly right-of-way line along a tangential curve concave westerly, chord South 12 deg. 04 min. 11.5 sec. West 61.40 feet, radius 65.00 feet, central angle 56 deg. 21 min. 57 sec. 63.95 feet to the point of beginning; thence South 12 deg. 02 min. 37 sec. West 245.10 feet to the southwesterly line of Government Lot 3 of the said Section 18; thence North 59 deg. 12 min. 49 sec. West along the said southwesterly line 135.44 feet; thence North 24 deg. 20 min. 31 sec. East 180.21 feet to the southerly right-of-way line of Frederic Court; thence along the said southerly right-of-way line along curve concave northerly, chord North 86 deg. 11 min. 49.5 sec. East 93.43 feet, radius 65.00 feet, central angle 91 deg. 53 min. 19 sec. 104.24 feet to the point of beginning, subject to the easement recorded in Vol. 956 Records, Page 622.

AND;

Part of Section Eighteen (18), Township Twenty-four (24) North, Range Twenty (20) East, in the Village of Howard, Brown County, Wisconsin, described as follows:

Commencing at the northwesterly corner of Government Lot 2, Section 18, Township 24 North, Range 20 East, Village of Howard, Brown County, Wisconsin; thence South 16 deg. 23 min. 39 sec. West 1249.07 feet to the easterly right-of-way line of Frederic Court; thence along the said easterly right-of-way line along a curve concave easterly, chord South 3 deg. 44 min. 40 sec. West 44.16 feet, radius 65.00 feet, central angle 39 deg. 42 min. 54 sec. 45.06 feet; thence continuing along the said easterly right-of-way line along a tangential curve concave westerly, chord South 12 deg. 04 min. 11.5 sec. West 61.40 feet, radius 65.00 feet, central angle 56 deg. 21 min. 57 sec. 63.95 feet; thence South 12 deg. 02 min. 37 sec. West 245.10 feet to the point of beginning; thence continuing South 12 deg. 02 min. 37 sec. West 16.60 feet to the northeasterly right-of-way line of S.T.H. "29-32"; thence North 60 deg. 34 min. 24 sec. West along the said northeasterly right-of-way line 138.67 feet; thence North 24 deg. 20 min. 31 sec. East 19.13 feet to the northeasterly line of the said Lot 1, Section 18, Township 24 North, Range 20 East, Town of Hobart, Brown County, Wisconsin; thence South 59 deg. 12 min. 49 sec. East along the said northeasterly line 135.44 feet to the point of beginning, subject to the easement recorded in Vol. 956 Records, Page 622.



LEGEND

-  MONITORING WELL
-  UNDERGROUND TELEPHONE
-  UNDERGROUND ELECTRIC
-  UNDERGROUND GAS
-  POTABLE WELL
-  FORMER UST LOCATION

FIGURE 2
 GEOPROBE BORING CONFIGURATION
 CANTERBURY FARM & GREENHOUSES
 HOWARD, WISCONSIN

SCALE	SHEET NO.	DWG NO.	DATE	SIZE	DRWN BY	REV	CHK'D	APP'D
1" = 30'	1 OF 1	PD2185.40.3.2	05/06/05	A	SVD			

Table 2
 Historical Groundwater Sample Laboratory Analytical Results
 Canterbury Farm and Greenhouses
 Howard, Wisconsin

Sample Date	Benzene	Ethylbenzene	Toluene	Total Xylenes	Total TMB's	MTBE	Naphthalene	EDB	1,2-DCA	n-butylbenzene	sec-butylbenzene	tert-butylbenzene	Isopropylbenzene	p-Isopropyltoluene	n-Propylbenzene	Lead	GW Depth (msl)
GP-10																	
8/14/2002	16,000	4,590	30,100	23,800	7,010	2,960	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
MW-1																	
Top of Well Screen (msl): 694.67 Length of Well Screen: 10 feet																	
8/20/2002	4,970	1,890	13,200	8,870	1,670	269	250	22.6	<10.0	66.2	36.4	<10.0	54.8	39.4	133	26.0	684.37
11/21/2002	2,950	1,180	6,750	6,700	1,477	181	337	NA	NA	NA	NA	NA	NA	NA	NA	57.4	662.91
MONITORING WELL MW-1 ABANDONED DURING EXCAVATION																	
MW-1R																	
Top of Well Screen (msl): Length of Well Screen: 10 feet																	
3/31/2003	540	54	78	1,040	270	65	72	NA	NA	NA	NA	NA	NA	NA	NA	1.7	13.65*
6/29/2003	250	26	290	1,100	350	23	51	NA	NA	NA	NA	NA	NA	NA	NA	NA	9.10*
9/29/2003	550	290	440	1,330	710	49	130	NA	NA	NA	NA	NA	NA	NA	NA	NA	10.10*
12/31/2003	600	440	720	1,300	810	77	130	NA	NA	NA	NA	NA	NA	NA	NA	NA	10.74
3/25/2004	290	180	100	400	256	28	54	NA	NA	NA	NA	NA	NA	NA	NA	NA	10.23
MW-2																	
Top of Well Screen (msl): 693.48 Length of Well Screen: 10 feet																	
8/20/2002	<0.50	<0.50	<0.50	<0.50	<2.0	<0.50	<2.0	<0.38	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<1.5	684.98
11/21/2002	<0.50	<0.50	<0.50	<0.50	<2.0	<0.20	<2.0	NA	NA	NA	NA	NA	NA	NA	NA	1.02	682.52
3/31/2003	<0.61	<0.63	<0.64	<2.12	<1.31	<0.62	<0.62	NA	NA	NA	NA	NA	NA	NA	NA	<0.94	681.93
6/29/2003	<0.45	<0.47	<0.61	<1.59	<1.23	<0.60	<0.46	NA	NA	NA	NA	NA	NA	NA	NA	NA	688.32
9/29/2003	<0.45	<0.47	<0.61	<1.59	<1.23	<0.60	<0.46	NA	NA	NA	NA	NA	NA	NA	NA	NA	685.13
12/31/2003	<0.29	<0.26	<0.34	<0.86	<0.70	<0.31	<0.39	NA	NA	NA	NA	NA	NA	NA	NA	NA	684.81
MW-3																	
Top of Well Screen (msl): 695.12 Length of Well Screen: 10 feet																	
8/20/2002	<0.50	<0.50	<0.50	<0.50	<2.0	<0.50	<2.0	<0.38	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<1.5	684.18
11/21/2002	<0.50	<0.50	<0.50	<0.50	<2.0	<0.20	<2.0	NA	NA	NA	NA	NA	NA	NA	NA	0.674	682.77
3/31/2003	<0.61	<0.63	<0.64	<2.12	<1.31	<0.62	<0.62	NA	NA	NA	NA	NA	NA	NA	NA	<0.94	680.87
6/29/2003	<0.45	<0.47	<0.61	<1.59	<1.23	<0.60	<0.46	NA	NA	NA	NA	NA	NA	NA	NA	NA	685.59
12/31/2003	<0.6	<0.47	<0.61	<1.59	<1.23	<0.60	<0.460	NA	NA	NA	NA	NA	NA	NA	NA	NA	684.03
MW-4																	
Top of Well Screen (msl): 695.01 Length of Well Screen: 10 feet																	
8/20/2002	<0.50	<0.50	<0.50	<0.50	<2.0	<0.50	<2.0	<0.38	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<1.5	684.54
11/21/2002	<0.50	<0.50	<0.50	<0.50	<2.0	<0.20	<2.0	NA	NA	NA	NA	NA	NA	NA	NA	<0.298	682.96
3/31/2003	<0.61	<0.63	<0.64	<2.12	<1.31	<0.62	<0.62	NA	NA	NA	NA	NA	NA	NA	NA	<0.94	681.23
6/29/2003	<0.45	<0.47	<0.61	<1.59	<1.23	<0.60	<0.46	NA	NA	NA	NA	NA	NA	NA	NA	NA	685.59
12/31/2003	<0.45	<0.47	<0.61	<1.59	<1.23	<0.60	<0.46	NA	NA	NA	NA	NA	NA	NA	NA	NA	684.17
MW-5																	
Top of Well Screen (msl): 693.65 Length of Well Screen: 10 feet																	
8/20/2002	3,840	1,890	8,860	9,820	1,778	2,280	189	65.2	44.0	75.8	17.9	<10.0	51.4	14.5	104	<1.5	683.61
11/21/2002	4,840	1,910	7,320	7,190	1,933	1,180	259	NA	NA	NA	NA	NA	NA	NA	NA	0.356	682.26
3/31/2003	4,100	1,800	3,690	5,900	1,459	1,600	280	NA	NA	NA	NA	NA	NA	NA	NA	<0.94	681.29
6/29/2003	730	280	700	870	388	280	39	NA	NA	NA	NA	NA	NA	NA	NA	NA	685.47
9/29/2003	1,300	520	750	1,930	620	900	120	NA	NA	NA	NA	NA	NA	NA	NA	NA	684.14
12/31/2003	1,100	330	220	640	208	330	67	NA	NA	NA	NA	NA	NA	NA	NA	NA	683.68
MW-10																	
Top of Well Screen (msl): 692.05 Length of Well Screen: 10 feet																	
9/8/2002	<0.50	<0.50	<0.50	<0.50	<2.0	<0.50	<2.0	<0.38	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	NA	680.21
11/21/2002	<0.50	<0.50	<0.50	<0.50	<2.0	<0.20	<2.0	NA	NA	NA	NA	NA	NA	NA	NA	<0.298	680.50
3/31/2003	<0.61	<0.63	<0.64	<2.12	<1.31	<0.62	<0.62	NA	NA	NA	NA	NA	NA	NA	NA	<0.94	678.23
6/29/2003	<0.45	<0.47	<0.61	<1.59	<1.23	<0.60	<0.46	NA	NA	NA	NA	NA	NA	NA	NA	NA	683.31
9/29/2003	<0.45	<0.47	<0.61	<1.59	<1.23	<0.60	<0.46	NA	NA	NA	NA	NA	NA	NA	NA	NA	682.07
12/31/2003	<0.45	<0.47	<0.61	<1.59	<1.23	<0.6	<0.46	NA	NA	NA	NA	NA	NA	NA	NA	NA	682.17
MW-11																	
Top of Well Screen (msl): 691.60 Length of Well Screen: 10 feet																	
9/8/2002	<0.50	<0.50	<0.50	<0.50	<2.0	<0.50	<2.0	<0.38	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	NA	681.21
11/21/2002	<0.50	<0.50	<0.50	<0.50	<2.0	<0.20	<2.0	NA	NA	NA	NA	NA	NA	NA	NA	0.539	680.44
3/31/2003	<0.61	<0.63	<0.64	<2.12	<1.31	<0.62	<0.62	NA	NA	NA	NA	NA	NA	NA	NA	<0.94	678.20
6/29/2003	<0.45	<0.47	<0.61	<1.59	<1.23	<0.60	<0.46	NA	NA	NA	NA	NA	NA	NA	NA	NA	683.27
9/29/2003	<0.45	<0.47	<0.61	<1.59	<1.23	<0.60	<0.46	NA	NA	NA	NA	NA	NA	NA	NA	NA	682.02
12/31/2003	<0.29	<0.26	<0.34	<0.89	<0.7	<0.31	<0.39	NA	NA	NA	NA	NA	NA	NA	NA	NA	682.16
PZ-1																	
Top of Well Screen (msl): 690.99 Length of Well Screen: 5 feet																	
9/18/2002	<0.50	<0.50	<0.50	0.730	1.21	<0.50	<2.0	<0.38	<0.50	<0.50	<0.50	0.934	<0.50	<0.50	<0.50	NA	674.74
11/21/2002	<0.50	<0.50	<0.50	<0.50	<2.0	<0.20	<2.0	NA	NA	NA	NA	NA	NA	NA	NA	<0.298	675.97
3/31/2003	<0.61	<0.63	<0.64	<2.12	<1.31	<0.62	<0.62	NA	NA	NA	NA	NA	NA	NA	NA	NA	674.79
6/29/2003	<0.45	<0.47	<0.61	<1.59	<1.23	<0.60	<0.46	NA	NA	NA	NA	NA	NA	NA	NA	NA	678.59
12/31/2003	<0.45	<0.47	<0.61	<1.59	<1.23	<0.60	<0.46	NA	NA	NA	NA	NA	NA	NA	NA	NA	678.29
Potable Well																	
8/20/2002	<0.50	<0.50	<0.50	<0.50	<2.0	<0.50	<2.0	<0.38	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<0.50	<1.5	NA
NR 140 ES	5	700	1,000	10,000	480	60	40	0.05	850	NS	NS	NS	NS	NS	NS	15	NA
NR 140 PAL	0.5	140	200	1,000	96	12	8	0.005	85	NS	NS	NS	NS	NS	NS	1.5	NA

Note: All concentrations reported in parts per billion
 Bold value represents exceedence of NR 140 enforcement standard
 Italicized values represent exceedence of NR 140 preventive action limits
 * feet below ground surface
 TMB: trimethylbenzene
 MTBE: methyl tert-butyl ether
 EDB: 1,2-Dibromoethane


1,2-DCA: 1,2-Dichloroethane
 NA: not analyzed/not applicable
 NS: no standard
 NR: Natural Resources
 ES: Enforcement Standard
 PAL: Preventive Action Limit

Table 1
 Historical Soil Sample Laboratory Analytical Results
 Canterbury Farm and Greenhouses
 Howard, Wisconsin

Sample ID	Sample Date	Sample Interval (ft bgs)/Depth	PID (ppm eq)	GRO	Benzene	Ethyl-benzene	Toluene	Total Xylenes	Naphthalene	1,2,4-TMB	1,3,5-TMB	MTBE	n-butyl-benzene	sec-butyl-benzene	Isopropyl-benzene	Lead
GP-1, S-3	5/24/2002	4.0-6.0	450	1,270	6,400	18,000	40,100	126,000	N/A	79,800	29,500	2,030	N/A	N/A	N/A	N/A
GP-1, S-5	5/24/2002	8.0-10.0	560	3,460	30,000	68,400	216,000	372,000	N/A	159,000	54,100	3,750	N/A	N/A	N/A	N/A
GP-10, S-2	8/14/2002	2 - 4	12.4	<5.21	45.2	71.9	274	352	<25.0	96.0	<25.0	<25.0	<25.0	<25.0	<25.0	4.81
GP-10, S-3	8/14/2002	4 - 6	>1000	1,670	15,400	55,300	140,000	399,000	38,800	198,000	61,700	<5000	26,400	<5000	6,680	2.85
GP-10, S-8	8/14/2002	14 - 16	42.0	<6.15	429	151	439	879	<25.0	522	171	<25.0	136	<25.0	<25.0	3.03
GP-11, S-6	8/14/2002	10 - 12	7.3	<6.04	305	53.5	40.3	335	<25.0	80.1	<25.0	<25.0	<25.0	<25.0	<25.0	2.38
GP-12, S-4	8/14/2002	6 - 8	10.8	6.82	950	242	1,840	1,620	149	432	148	171	55.7	<25.0	<25.0	1.87
GP-13, S-6	8/14/2002	10 - 12	0.0	<6.18	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	3.22
GP-14, S-6	8/14/2002	10 - 12	0.0	<5.93	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	2.57
GP-15, S-6	8/14/2002	10 - 12	>1000	302	2,650	5,600	15,700	33,800	3,380	20,100	6,590	<500	6,570	1,610	866	1.60
GP-16, S-6	8/14/2002	10 - 12	0.0	<6.09	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	2.94
MW-1, S-2	8/16/2002	2 - 4	48.0	<5.99	<25.0	33.4	59.4	127	<25.0	<25.0	<25.0	<25.0	80.7	52.0	<25.0	17.6
MW-1, S-8	8/16/2002	14 - 16	9.0	<6.11	163	145	63.6	641	169	585	199	<25.0	161	48.6	<25.0	3.74
MW-3, S-1	8/16/2002	10 - 12	0.0	NA	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	NA
MW-4, S-1	8/16/2002	10 - 12	0.0	<6.22	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	3.48
MW-4, S-4	8/16/2002	16 - 18	0.0	<6.11	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	NA
MW-5, S-3	8/16/2002	12 - 14	26.0	10.0	791	530	1,900	3,030	201	878	252	285	119	<25.0	31.1	3.18
MW-10, S-3	9/6/2002	10 - 12	0.0	<5.56	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	NA	NA	NA	NA
MW-11, S-2	9/6/2002	10 - 12	0.0	<5.55	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	<25.0	NA	NA	NA	NA
WW-1	12/23/2002	11.0	N/A	<5.00	434	162	686	1,220	N/A	360	118	310	N/A	N/A	N/A	N/A
WW-2	12/23/2002	11.0	N/A	6.78	1,640	264	2,080	1,450	N/A	575	202	444	N/A	N/A	N/A	N/A
Floor-1	12/23/2002	13.5	N/A	<6.49	<25.0	<25.0	43.1	<25.0	N/A	<25.0	<25.0	<25.0	N/A	N/A	N/A	N/A
NW-3	12/23/2002	13.0	N/A	10.3	1,360	333	2,730	2,400	N/A	598	189	246	N/A	N/A	N/A	N/A
NW-4	12/23/2002	13.5	N/A	19.4	2,960	556	4,970	3,790	N/A	893	267	<25.0	N/A	N/A	N/A	N/A
EW-5	12/23/2002	13.5	N/A	4430	4,620	41,400	37,700	230,000	N/A	156,000	63,000	<500	N/A	N/A	N/A	N/A
SW-7	12/23/2002	13.0	N/A	10.9	1,070	524	2,360	3,430	N/A	920	274	372	N/A	N/A	N/A	N/A
SW-8	12/23/2002	12.0	N/A	26.1	1,560	382	2,390	3,680	N/A	1,880	606	118	N/A	N/A	N/A	N/A
EW-9	12/23/2002	11.0	N/A	<6.00	376	124	829	830	N/A	319	128	<25.0	N/A	N/A	N/A	N/A
Floor-2	12/23/2002	13.5	N/A	9.48	184	428	290	2,130	N/A	941	297	<25.0	N/A	N/A	N/A	N/A
NR 720.09 RCLs				100	5.5	2,900	1,500	4,100	NS	NS	NS	NS	NS	NS	NS	50
NR 746.06 Table 1 (free product indicator)				NS	8,500	4,600	38,000	42,000	2,700	83,000	11,000	NS	NS	NS	NS	NS
NR 746.06 Table 2 (direct contact standard)				NS	1,100	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS

Notes:

All concentrations reported in parts per billion, except GRO and Lead reported in parts per million
Bold value represents an exceedence of the WDNR NR720 Generic Soil Standard
 bgs: below ground surface
 ppm eq: part per million equivalent
 GRO: gasoline range organics
 TMB: trimethylbenzene
 MTBE: methyl tert-butyl ether
 NA: not analyzed/not applicable
 NS: no standard
 WDNR: Wisconsin Department of Natural Resources




LEGEND

- MONITORING WELL
- UNDERGROUND TELEPHONE
- UNDERGROUND ELECTRIC
- UNDERGROUND GAS
- POTABLE WELL
- GEOPROBE SOIL BORING LOCATION
- FORMER UST LOCATION
- NR140 ES EXCEEDANCE



FIGURE 3
 EXTENT OF GROUNDWATER
 CONTAMINATION
 CANTERBURY FARM & GREENHOUSES
 HOWARD, WISCONSIN

SCALE	SHEET NO.	DWG NO.	DATE	SIZE	DRWN BY	REV	CHK'D	APP'D
1" = 30'	1 OF 1	PQ2185.40.3.1	05/06/05	A	JMR			



FREDERICK COURT

ASPHALT

ASPHALT DRIVE

ASPHALT DRIVE

SOIL HOUSE

GARAGE

ASPHALT

WELL HOUSE

SILO

BARN

GREENHOUSE

ASPHALT

WELL


LEGEND

- MONITORING WELL
- UNDERGROUND TELEPHONE
- UNDERGROUND ELECTRIC
- UNDERGROUND GAS
- POTABLE WELL
- GROUNDWATER SURFACE CONTOUR
- 685.47 GROUNDWATER ELEVATION
- GROUNDWATER FLOW DIRECTION



FIGURE 4
 6/29/2003 POTENTIOMETRIC SURFACE MAP
 CANTERBURY FARM & GREENHOUSES
 HOWARD, WISCONSIN

SCALE	SHEET NO.	DWG NO.	DATE	SIZE	DRWN BY	REV	CHK'D	APP'D
1" = 30'	1 OF 1	PO2185.40.4.1	05/06/05	A	JMR			




LEGEND

- MONITORING WELL
- UNDERGROUND TELEPHONE
- UNDERGROUND ELECTRIC
- UNDERGROUND GAS
- POTABLE WELL
- GROUNDWATER SURFACE CONTOUR
- 684.03 GROUNDWATER ELEVATION
- GROUNDWATER FLOW DIRECTION

FIGURE 5
 12/31/2003 POTENTIOMETRIC
 SURFACE MAP
 CANTERBURY FARM & GREENHOUSES
 HOWARD, WISCONSIN

SCALE	SHEET NO.	DWG NO.	DATE	SIZE	DRWN BY	REV	CHK'D	APP'D
1" = 30'	1 OF 1	PD2185.40.51	05/06/05	A	JMR			



- LEGEND**
- MONITORING WELL
 - UNDERGROUND TELEPHONE
 - UNDERGROUND ELECTRIC
 - UNDERGROUND GAS
 - POTABLE WELL
 - FORMER UST LOCATION
 - SOIL BENZENE CONCENTRATION (ppb)
 - EXTENT OF RESIDUAL SOIL CONTAMINATION ABOVE NR720 RCLs
 - EXCAVATION AREA


FIGURE 6
 EXTENT OF
 RESIDUAL SOIL CONTAMINATION
 CANTERBURY FARM & GREENHOUSES
 HOWARD, WISCONSIN

SCALE	SHEET NO.	DWG NO.	DATE	SIZE	DRWN BY	REV	CHK'D	APP'D
1" = 30'	1 OF 1	PD2185.40.1.1	5/06/05	A	JMR	61		



2280-B SALSCHIEDER COURT, GREEN BAY, WI 54313

HORIZONTAL SCALE 1" = 30'



- LEGEND**
- RESIDUAL SOIL ABOVE NR720 RCLs
 - SM - SILTY SAND
 - CL - CLAY
 - BACK FILL
 - 222** BENZENE CONCENTRATION (ppb)
 - (222)** PID
 - EXCAVATION LIMITS

FIGURE 7
CROSS SECTION
CANTERBURY FARM & GREENHOUSES
HOWARD, WISCONSIN

SCALE	SHEET NO.	DWG NO.	DATE	SIZE	DRWN BY	REV	CHK'D	APP'D
1" = 30'	1 OF 1	P02185.40.7.1	05/06/05	A	JMR			

Mr. Harold Thompson
2867 Drake Place
Green Bay, Wisconsin 54313

May 6, 2005

Mr. Robert H. Klauk
PECFA Bureau, Environmental and Regulatory Services Division
Wisconsin Department of Commerce
2129 Jackson Street
Oshkosh, Wisconsin 54901-1805

RE: GIS Registry Packet and Closure Request
Canterbury Farm & Greenhouses **WDNR BRRTS No. 03-05-307271**
Endeavor Project No. P02185.40 **Commerce No. 54313-7317-14**

Dear Mr. Klauk,

I believe that the legal descriptions for the above-referenced property, parcel number VH-507, listed below and attached to this statement are complete and accurate.

The address of the property is 614 Frederic Court, Village of Howard, Brown County, Wisconsin as legally described on the attached sheet.

This statement is in conjunction with the Wisconsin Department of Natural Resources GIS Registry Packet, PUB-RR-688.

Sincerely,



Harold Thompson
Responsible Party Representative

Cc: Endeavor, File

ADDENDUM TO WARRANTY DEED

GRANTOR: Harold W. Thompson and Randall B. Pierret
 GRANTEE: TAAD Lawn Care, LLC

Description of property conveyed:

Part of Government Lots Two (2) and Three (3), Section Eighteen (18), Township Twenty-four (24) North, Range Twenty (20) East, in the Village of Howard, Brown County, Wisconsin, described as follows:

Commencing at the northwesterly corner of Government Lot 2 of the said Section 18; thence South 16 deg. 23 min. 39 sec. West 1249.07 feet to a point on the easterly right-of-way line of Frederic Court, said point being the point of beginning; thence south 65 deg. 05 min. 20 sec. East along the southwesterly line of Lot 1 Vol. 3 Certified Survey Maps Page 523, 854.82 feet; thence South 1 deg. 14 min. 40 sec. West along the extension of the easterly line of the said Lot 1, Vol 3. Certified Survey Maps, Page 523, 426.23 feet to the northeasterly right-of-way line of S.T.H. "29-32"; thence North 65 deg. 39 min. 10 sec. West along the said northeasterly right-of-way line 412.56 feet to the southwesterly line of Government Lot 2 of the said Section 18; thence North 59 deg. 12 min. 49 sec. West along the said southwesterly line and along the southwesterly line of Government Lot 3 of the said Section 18 a distance of 531.99 feet; thence North 12 deg. 02 min. 37 sec. East 245.10 feet to the easterly right-of-way line of Frederic Court; thence along the said easterly line along a curve concave westerly, chord North 12 deg. 04 min. 11.5 sec. East 61.40 feet, radius 65.00 feet, central angle 56 deg. 21 min. 57 sec. 63.95 feet; thence continuing along the said easterly right-of-way line along a tangential curve concave easterly, chord North 3 deg. 44 min. 40 sec. East 44.16 feet, radius 65.00 feet, central angle 39 deg. 42 min. 54 sec. 45.06 feet to the point of beginning, subject to the easement recorded in Vol. 956 Records, Page 622.

AND;

Part of Government Lot Three (3), Section Eighteen (18), Township Twenty-four (24) North, Range Twenty (20) East, in the Village of Howard, Brown County, Wisconsin described as follows:

Commencing at the northwesterly corner of Government Lot 2 of the said Section 18; thence South 16 deg. 23 min. 39 sec. West 1249.07 feet to the easterly right-of-way line of Frederic Court; thence along the said easterly right-of-way line along a curve concave easterly, chord South 3 deg. 44 min. 40 sec. West 44.16 feet, radius 65.00 feet, central angle 39 deg. 42 min. 54 sec. 45.06 feet; thence continuing along the said easterly right-of-way line along a tangential curve concave westerly, chord South 12 deg. 04 min. 11.5 sec. West 61.40 feet, radius 65.00 feet, central angle 56 deg. 21 min. 57 sec. 63.95 feet to the point of beginning; thence South 12 deg. 02 min. 37 sec. West 245.10 feet to the southwesterly line of Government Lot 3 of the said Section 18; thence North 59 deg. 12 min. 49 sec. West along the said southwesterly line 135.44 feet; thence North 24 deg. 20 min. 31 sec. East 180.21 feet to the southerly right-of-way line of Frederic Court; thence along the said southerly right-of-way line along curve concave northerly, chord North 86 deg. 11 min. 49.5 sec. East 93.43 feet, radius 65.00 feet, central angle 91 deg. 53 min. 19 sec. 104.24 feet to the point of beginning, subject to the easement recorded in Vol. 956 Records, Page 622.

AND;

Part of Section Eighteen (18), Township Twenty-four (24) North, Range Twenty (20) East, in the Village of Howard, Brown County, Wisconsin, described as follows:

Commencing at the northwesterly corner of Government Lot 2, Section 18, Township 24 North, Range 20 East, Village of Howard, Brown County, Wisconsin; thence South 16 deg. 23 min. 39 sec. West 1249.07 feet to the easterly right-of-way line of Frederic Court; thence along the said easterly right-of-way line along a curve concave easterly, chord South 3 deg. 44 min. 40 sec. West 44.16 feet, radius 65.00 feet, central angle 39 deg. 42 min. 54 sec. 45.06 feet; thence continuing along the said easterly right-of-way line along a tangential curve concave westerly, chord South 12 deg. 04 min. 11.5 sec. West 61.40 feet, radius 65.00 feet, central angle 56 deg. 21 min. 57 sec. 63.95 feet; thence South 12 deg. 02 min. 37 sec. West 245.10 feet to the point of beginning; thence continuing South 12 deg. 02 min. 37 sec. West 16.60 feet to the northeasterly right-of-way line of S.T.H. "29-32"; thence North 60 deg. 34 min. 24 sec. West along the said northeasterly right-of-way line 138.67 feet; thence North 24 deg. 20 min. 31 sec. East 19.13 feet to the northeasterly line of the said Lot 1, Section 18, Township 24 North, Range 20 East, Town of Hobart, Brown County, Wisconsin; thence South 59 deg. 12 min. 49 sec. East along the said northeasterly line 135.44 feet to the point of beginning, subject to the easement recorded in Vol. 956 Records, Page 622.



May 6, 2005

TAAD Lawn Care, LLC.
614 Frederic Court
Green Bay, Wisconsin 54313

**RE: Residual Contamination Notification
GIS Registry Packet and Closure Request
Canterbury Farm & Greenhouses
Endeavor Project No. P02185.40**

**WDNR BRRTS No. 03-05-307271
Commerce No. 54313-7317-14**

To Whom It May Concern:

Groundwater contamination that originated on the property located at 614 Frederic Court remains on the property and has migrated into a portion of the right-of-way. The levels of benzene, methyl-tert-butyl ether (MTBE), and naphthalene contamination in the groundwater on your property are above the state groundwater enforcement standards found in NR 140, Wisconsin Administrative Code. However, Endeavor Environmental Services, Inc. (Endeavor) has investigated this contamination and has determined that the groundwater contaminant plume is stable or receding and will naturally degrade over time. Endeavor believes that allowing natural attenuation to complete cleanup at this site will meet the requirements for case closure that are found in chapter NR 726 and chapter Comm 46, Wisconsin Administrative Code, and Endeavor will be requesting that the Department of Commerce accept natural attenuation as the final remedy for this site and grant case closure. Closure means that the Department will not be requiring any further investigation or cleanup action to be taken, other than the reliance on natural attenuation.

Since the source of the groundwater contamination is on your property, neither you nor any subsequent owner of your property will be held responsible for investigation or cleanup of this groundwater contamination, as long as you and any subsequent owners comply with the requirements of section 292.12, Wisconsin Statutes, including allowing access to your property for environmental investigation or cleanup if access is required. For further information on the requirements of section 292.13, Wisconsin Statutes, you may call 1-800-367-6076 for calls originating in Wisconsin, or 608-264-6020 if you are calling from out of state or within the Madison area.

The Department of Commerce will not review the closure request for at least 30 days after the date of this letter. As an affected property owner, you have the right to contact the Department to provide and technical information that you may have that indicates that closure should not be granted for this site. If you would like to submit any information to the Department of Commerce that is relevant to this closure request, you should mail that information to:

Robert H. Klauk,
PECFA Bureau, Environmental and Regulatory Services Division
Wisconsin Department of Commerce
2129 Jackson Street
Oshkosh, Wisconsin 54901-1805

If this case is closed, all properties within the site boundaries where groundwater contamination exceeds chapter NR 140 groundwater enforcement standards will be listed on the Department of Natural Resources' geographic information system (GIS) Registry of Closed Remediation Sites. The information on the GIS Registry includes maps showing the location of properties in Wisconsin where groundwater contamination above chapter NR 140 enforcement standards was found at the time the case was closed. This GIS Registry will be available to the general public on the Department of Natural Resources' internet web site. Please review the enclosed legal description of your property, and notify Endeavor within the next 30 days if the legal description is incorrect.

Should you or any subsequent property owner wish to construct or reconstruct a well on your property, special well construction standards may be necessary to protect the well from the residual groundwater contamination. Any well driller who proposes to construct a well on your property in the future will first need to call Diggers Hotline (1-800-242-8511) if your property is located outside of the service area of a municipally owned water system, or contact the Drinking Water program within the Department of Natural Resources if your property is located within the designated service area of a municipally owned water system, to determine if there is a need for special well construction standards.

Once the Department makes a decision on the closure request, it will be documented in a letter. If the Department grants closure, you may obtain a copy of this letter is included as part of the site file on the GIS Registry of Closed Remediation Sites.


If you require more information, you may contact Endeavor at the following address:

Endeavor Environmental Services, Inc.
2280B Salscheider Court
Green Bay, Wisconsin 54313
(920) 437-2997

Or you may contact the Department of Commerce Project Manager at:

Robert H. Klauk,
PECFA Bureau, Environmental and Regulatory Services Division
Wisconsin Department of Commerce
2129 Jackson Street
Oshkosh, Wisconsin 54901-1805

Sincerely,
Endeavor Environmental Services, Inc.,


Joseph M. Ramcheck, P.H.
Senior Hydrologist

cc: Harold Thompson
File



May 6, 2005

Village of Howard
Department of Public Works
Engineering Department
1336 Cornell Road
Green Bay, Wisconsin 54313

**RE: Notification of Contamination within the Right-of-Way
Canterbury Farm & Greenhouses
614 Frederic Court
Village of Howard
Endeavor Project No. P02185.40**

**WDNR BRRTS No. 03-05-307271
Commerce No. 54313-7317-14**

Notification of Contamination within the Right-of-Way

County: Brown
Street: Frederic Court
Site Name: Canterbury Farm and Greenhouses
Site Address: 614 Frederic Court, Green Bay, Wisconsin 54313
BRRTS Number: 03-05-307271
PECFA Number: 54313-7317-14
FID Number: None
Owner's Name: Harold Thompson
Owner's Address: 2867 Drake Place, Green Bay, Wisconsin 54313

Consulting Firm: Endeavor Environmental Services, Inc.
Consultant Contact: Joseph M. Ramcheck, P.H.
Consultant Address: 2280-B Salscheider Ct, Green Bay, WI 54313
Phone: (920) 437-2997, Fax (920) 437-3066, E-mail: jramcheck@endeavorenv.com

Soil Contamination: yes
Depth to contaminated soil: 8 feet
Vertical extent of contaminated soil: 8 to 18 feet below ground surface
Groundwater contamination: yes
Depth to water table: 8 to 13 feet

Describe the type(s) of contamination present:

Gasoline range organic compounds (GRO), benzene, ethylbenzene, toluene, trimethylbenzenes, xylenes and naphthalene were detected in soil on the subject site. It is Endeavor's professional opinion, based on the site gradient and soil properties, that it is likely that residual soil contamination will be located in the Frederic Court "right-of-way". Benzene, ethylbenzene, toluene, trimethylbenzenes, and xylenes were detected



above their respective Wisconsin Administrative Code (WAC) Chapter NR 720 Residual Contaminant Levels (RCLs) and above WAC Chapter NR 746 Table 1 values.

Benzene, ethylbenzene, toluene, trimethylbenzenes, xylenes, MTBE and naphthalene detections remain in groundwater on the subject site. It is Endeavor's professional opinion, based on site groundwater gradient, that it is likely that residual groundwater contamination will be located in the Frederic Court "right-of-way". Benzene, MTBE, and naphthalene remain above their respective WAC NR 140 Enforcement Standards (ES). Ethylbenzene, toluene, trimethylbenzenes, and xylenes also remain above the WAC NR 140 Preventative Action Limit (PAL).

Brief summary of the cleanup activity:

Accessible petroleum contamination was excavated and properly disposed. Long-term remediation at the site will consist of natural attenuation of residual soil and groundwater contamination. No additional active remedial activities will be implemented.

The Wisconsin Department of Commerce has requested a review of the site for case closure.

Figures illustrating the extent of residual soil and groundwater contamination and tables illustrating the laboratory analytical data are attached.

If you have any questions regarding the enclosed information, please feel free to contact Endeavor at (920) 437-2997 at your convenience.

Sincerely,

A handwritten signature in black ink, appearing to read "J. M. Ramcheck", is written over a horizontal line.

Joseph M. Ramcheck, P.H.
Senior Hydrologist

enc: Figures, Tables

cc: M.r Harold Thompson – Responsible Party
Wisconsin Department of Commerce
file