

The following site is being submitted for inclusion into the Groundwater GIS registry:

- For DNR County and Region list go to:
g:\pfp\pecfa\site\gis\BRRTS County and Region Codes.xls
- To begin, click on cell to the right of; *This is a:*
- Use Tab, ↓ or Pg Down to navigate form. Print & include with file when completed.

This is a:	New Submittal
BRRTS ID (no dashes):	0349000982
Comm # (no dashes):	54858902996
County:	Polk
Region:	Northern
Site name:	Bumper to Bumper/Rapid Repair
Street Address:	96 E Main St
City:	Milltown
Final Closure Date	2002-10-24
Closure Conditions:	met
Off-source property contamination? (If yes, attach locational data and deed information on pg. 2)	No
Right-of-way contamination?	No
Contaminated media:	Groundwater
GPS Coordinates (meters in the WTM91 projection)	
Easting (X):	324561
Northing (Y):	564487
Collection Method:	DNR Web Site
Scale or Resolution:	1:3,839
(1:24,000 scale or finer)	
Prepared by:	Shawn Wenzel
Submitted by:	Cheryl Nelson

Source Property Checklist

- Final Closure Letter
- Copy of the most recent deed, which includes legal description for all properties w/ GW > NR 140 ES
- Where the legal description in the deed(s) refers to a certified survey map or recorded plat map, include those documents
- Parcel ID for all properties w/ GW > NR 140 ES
- General Location Map
- Detailed Location Map showing property boundaries, buildings, MW(s) and/or potable wells etc for properties with GW >NR140 ES
- Latest Map(s) showing extent or outline of current GW plume (isoconcentrations)
- Map showing GW flow direction
- Latest Table of GW results
- Geologic cross section (if generated as part of the site investigation)
- Statement signed by RP certifying correctness of legal descriptions
- Updated Database



October 24, 2002

Don Michaelson
215 Stokley Ave
Milltown, WI 54858

RE: **Final Closure**

Commerce # 54858-9029-96 **WDNR BRRTS # 03-49-000982**
Bumper To Bumper/Rapid Repair, 96 E Main St, Milltown

Dear Mr. Michaelson:

The Wisconsin Department of Commerce (Commerce) has received all items required for closure of the site referenced above. This site is now listed as "closed" on the Commerce database.

It is in your best interest to keep all documentation related to the environmental activities at your site. If residual contamination is encountered in the future, appropriate measures must be implemented to assure that it is managed following all applicable regulations. If future site conditions indicate that any remaining contamination poses a threat, and subsequent information indicates a need to reopen this case, any original claim under the PECFA fund would also reopen and you may apply for assistance to the extent of remaining eligibility.

Please note that the impermeable layer, as described in the October 18, 2001 correspondence submitted by your consultant, must be maintained per the Deed Restriction filed with the Polk County Register of Deeds on August 9, 2002.

Thank you for your efforts to protect Wisconsin's environment. If you have any questions, please contact me in writing at the letterhead address or by telephone at (608) 261-5401.

Sincerely,

Shawn A. Wenzel
Hydrogeologist
Site Review Section

cc: Keith Norlin, Three Bears Environmental Services
Case File

638189

Document Number

NOTICE OF CONTAMINATION TO PROPERTY

POLK COUNTY, WISCONSIN
Received for record this
9th day of August
AD 2002 at 10:45AM
and recorded in volume 912
of records page 159
Document Number: 638189

Jonnie L. Hallberg
Register of Deeds

Legal Description of the Property: In re:
(as it appears on the most recent deed)

SEE ATTACHED DESCRIPTION

Recording Area

Name and Return Address

DONALD L. MICHEALSON
P. O. BOX 189
MILLTOWN, WI 54858

151-314

Parcel Identification Number (PIN)

STATE OF WISCONSIN)
) ss
COUNTY OF POLK)

Section 1. DONALD L. MICHEALSON is the owner of the above-described property.

Section 2. One or more petroleum discharges have occurred at this property contaminating groundwater above NR 140 enforcement standards and soils above NR 720 residual contaminant levels of the Wisconsin Administrative Code exist(s) on this property.

Section 3. It is the desire and intention of the property owner to impose restrictions on the property which will make it unnecessary to conduct additional soil remediation activities on the property at the present time. The owner hereby declares that all of the property described above is held and shall be held, conveyed or encumbered, leased, rented, used, occupied and improved subject to the following limitations and/or restrictions:

Petroleum contaminated soil remains on this property. According to the report filed by Three Bears Environmental Services, dated February 20, 2001, the residual contaminated soils are located west of the former Bumper to Bumper building near the former underground storage tank (UST) basin as well as beneath the former waste oil UST formerly located along the east wall of the Rapid Repair building. An impermeable cap or cover is the selected remedial action to address residual soil contamination on the property. Therefore, an impermeable cap or cover (i.e. concrete, asphalt) shall be maintained across this property until: 1). The soil is actively remediated or removed or; 2). It can be shown that the soil has naturally degraded to levels shown to be protective of the environment and human health. If subsurface work is done in the contaminated areas, the contamination shall be properly treated or disposed of in accordance with applicable laws (File references: PECFA Claim number 54858-9029-96 and BRTS 03-49-000982).

15

638189

LEGAL DESCRIPTION

A parcel of land in the Northeast Quarter of the Northwest Quarter (NE1/4 of NW1/4) of Section Seventeen (17), Township Thirty-five (35) North of Range Seventeen (17) West, in an unplatted portion of the Village of Milltown, more particularly described as follows: Commencing at a point 891.25 feet West and 33 feet South of North ¼ corner of said Section 17, which is the point of beginning, then South at an angle of 90 to said section line, a distance of 147.0 feet to a one inch galvanized iron pipe stake and the right of way of the Minneapolis, St. Paul and Sault Ste. Marie Railway, then Northeasterly along said right of way line 218.89 feet to a one inch galvanized iron pipe stake set at the south edge of the concrete sidewalk, then West parallel to said Section line 161.75 feet to a one inch galvanized iron pipe stake and the point of beginning.

Also

The East 15.00 feet of Lot 2, Certified Survey Map No. 1724, Vol. 8 page 72, more particularly described as follows:

Beginning at the Northeast corner of said Lot 2; thence N 89 52' 28" West, along the north line of said Lot 2, 15.00 feet; thence S 00 07' 32" West, parallel to the east line of said Lot 2, 161.04 feet to the south line of said Lot 2; thence N 47 55' 44" East along said south line, 20.25 feet to the Southeast corner of said Lot 2; thence N 00 07' 32" East 147.44 feet to the point of beginning. Containing 2314 square feet.

Together with an access easement for ingress and egress to the above described Parcel A over and across the North 90 feet of the West 25 feet of the East 40 feet of said Lot 2 of Certified Survey Map No. 1724.

638189

Residual groundwater contamination above NR 720 enforcement standards remains on site and is located beneath the former UST basin located to the west of the former Bumper to Bumper building and extends to near Main Street making up the northern property line of the site. Natural attenuation is the approved remedial alternative for this site. Anyone who proposes to construct or reconstruct a well on this property is required to contact the Department of Natural Resources' Bureau of Drinking Water and Groundwater, or its successor agency, to determine what specific prohibitions or requirements are applicable, prior to constructing or reconstructing a well on this property. No well may be constructed or be constructed on this property unless applicable requirements are met.

Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Commerce, or its successor, issue a determination that the restrictions set forth in this covenant are no longer required. That property owner shall provide any and all necessary information to the Department in order for the Department to be able to make a determination. Upon receipt of such a request, the Department shall determine whether or not the restrictions contained herein can be extinguished. Conditions under which a restriction may be extinguished will be determined in accordance with the site specific standards, rules and laws for this property. If the Department determines that the restrictions can be extinguished, an affidavit, with a copy of the Department's written determination, may be recorded to give notice that this restriction, or portions of this restriction are no longer binding. Any restriction placed upon this property shall not be extinguished without the Department's written determination.

IN WITNESS WHEREOF, the owner of the property has executed this document, this 9th day of AUGUST, 2002.

[When appropriate use the following clause]:

By signing this document, [he/she] acknowledges that [he/she] is duly authorized to sign this document on behalf of N/A.

Signature: *Donald L. Michealson*



Printed Name: DONALD L. MICHEALSON

Title: _____

Subscribed and sworn to before me this 9th day of August, 2002

Stewart Davis
Notary Public, State of Wisconsin
My commission 8/28/05

This document was drafted by the Wisconsin Department of Commerce.



- ROAD CLASSIFICATION**
- Primary highway, hard surface _____
 - Secondary highway, hard surface _____
 - Light-duty road, hard or improved surface _____
 - Unimproved road _____
- Interstate Route
 U. S. Route
 State Route


MILLTOWN, WIS.
 SE/4 MILLTOWN 15' QUADRANGLE
 N4530-W9230/7.5

WISCONSIN 53706
 WEST

1983

FIGURE ONE; SITE LOCATION MAP

DMA 2475 II SE-SERIES V861




curb

nm#4

Main Street

North ↑




Legend:


- nm#1 monitoring well
- gp#1 Geoprobe location
- ASST propane
- former pump island
- former location of UST
- Village of Milwaukee Easement
- property line

3 Bears Environmental Services
 Groundwater Plume 3/00
 Bumper to Bumper/Rapid Repair
 Milltown, Wisconsin

Figure 2

0 18ft





3 Bears Environmental Services
 Groundwater Benzene Exceedance
 Bumper to Bumper/Rapid Repair
 Milltown, Wisconsin
 Figure 4

benzene exceeds
 NR 140 ES




Table 2

BUMPER TO BUMPER/RAPID REPAIR
Milltown, Wisconsin

Groundwater Sampling Analytical Results

Location	Date	Sample No.	Benzene ug/L	Toluene ug/L	Ethylbenzene ug/L	Xylenes ug/L	1,2,4-Tri-methylbenzene ug/L	1,3,5-Tri-methylbenzene ug/L	MTBE ug/L	GRO ug/L	DRO ug/L	Naphthalene ug/L	1,2 DCA ug/L
gp#1	7/26/97	261005/261010/2 61015	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	---	150	N.D.	---
gp#2	7/26/97	261145/261205/2 61230	N.D.	160	140	820	1,200	370	N.D.	16,000	65,000	350	---
MW#1	11/19/97	1336	N.D.	5.2	14	116	560	41	N.D.	---	A	32	---
MW#1	10/15/98	1389	8.2	28	220	1530	850	230	N.D.	---	2.1E+07	37000	---
MW#1	10/21/98	1395	13	24	120	780	550	160	5.1	---	2300	---	---
MW#1	12/2/98	1422	11	27	120	750	610	190	N.D.	4700	4400	---	---
MW#1	5/25/99	1309	7.7	19	130	800	430	110	4.9	4600	---	---	N.D.
MW#1	9/2/99	1554	4.9	21	110	760	540	150	N.D.	4400	---	---	N.D.
MW#1	3/21/00	1689	17	13.0	88	630	490	130	N.D.	3,600	2,400	110	N.D.
MW#2	11/19/97	1337	3.1Q	8.6	88	428	360	100	N.D.	---	---	30	---
MW#2	8/7/98	1287	110	15	150	334	330	75	3	2,800	---	---	---
MW#2	10/15/98	1391	150	12	140	410	310	81	4.9	---	1100	20	---
MW#2	12/2/98	1423	32	3.9	65	88	220	63	4.8	1800	---	---	---
MW#2	5/25/99	1310	42	7.5	71	137	220	35	3.6	1900	---	---	N.D.
MW#2	9/2/99	1555	47	9.5	28	73	29	8.4	1.2	700	940	3	N.D.
MW#2	3/21/00	1690	3.9	0.7	0.7	2.8	11	0.9	N.D.	200	---	1.1 Q	---
MW#3	11/19/97	1338	2.1	0.81 Q	2.0	5.30 Q1	4.0	1.2	N.D.	---	---	---	---
MW#3	8/7/98	1286	4	N.D.	N.D.	3	4	N.D.	N.D.	140	---	---	---
MW#3	10/15/98	1390	14	1.1	1.5	3.8	5.5	0.9	N.D.	---	N.D.	N.D.	---
MW#3	12/2/98	1424	13	1.7	1.7	9	6.5	1.5	N.D.	210	---	---	---
MW#3	5/25/99	1311	3.3	1.3	0.58	4.9	4.1	0.6	0.82	240	---	---	---
MW#3	9/2/99	1556	5.2	0.9	0.51	10.8	7.4	1.3	N.D.	270	---	---	N.D.
MW#3	3/21/00	1691	7.3	0.98	1.5	22	16	1.3	N.D.	270	---	---	N.D.
MW#4	11/19/97	1339	N.D.	N.D.	0.26 Q	1.35 Q	0.61 Q	N.D.	N.D.	---	---	N.D.	---
MW#4	8/7/98	1288	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	---	N.D.	---
MW#4	10/15/98	1392	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	---	N.D.	N.D.	---
MW#4	12/2/98	1425	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	---	---	---
MW#4	5/25/99	1312	N.D.	N.D.	N.D.	N.D.	N.D.	0.42	N.D.	N.D.	---	---	---
MW#5	9/2/99	1557	4.8	N.D.	N.D.	N.D.	1.3	0.38	0.49	140	N.D.	---	0.4 Q
MW#5	10/6/99	1608	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	---	---	N.D.
MW#5	3/21/00	1692	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	---	---	N.D.
NR 140 Enforcement Standard (ES)			5 ug/L	343 ug/L	700 ug/L	620 ug/L	NA	NA	60 ug/L	NA	NA	40 ug/L	5 ug/L
NR 140 Preventative Action Limit (PAL)			0.5 ug/L	68.6 ug/L	140 ug/L	124 ug/L	NA	NA	12 ug/L	NA	NA	8 ug/L	0.5 ug/L

GRO: gasoline range organics
ug/L.: micrograms per liter

---: not analyzed for this parameter

N.D.: not detected at or above laboratory method detection limit

Q: The parameter has been detected between the limit of detection (LOD) and the limit of quantification (LOQ).

DRO: diesel range organics

A: DRO is present; could not quantify due to a laboratory accident.

Bold type indicates that the value exceeds NR140ES.

MTBE: methyl tertiary butyl ether

1,2 DCA: 1,2-dichloroethane

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri-methylbenzene: toluene

Xylenes: o-xylene, m-xylene, p-xylene

Ethylbenzene: ethylbenzene

MTBE: methyl tertiary butyl ether

1,3,5-Tri-methylbenzene: mesitylene

1,2,4-Tri

Table 3

BUMPER TO BUMPER/RAPID REPAIR
Milkton, Wisconsin

Groundwater-Sampling Analytical Results
Polynuclear Aromatic Hydrocarbons

Location	Date	Sample No.	Anthracene ug/L	Benzo (a) anthracene ug/L	Benzo (e) pyrene ug/L	Benzo (b) fluoranthene ug/L	Benzo (g,h,i) perylene ug/L	Benzo (k) fluoranthene ug/L	Chrysene ug/L	Dibenzo (a,h) anthracene ug/L	Fluoranthene ug/L	Fluorene ug/L	Indeno (1,2,3-cd) pyrene ug/L	1-Methyl-naphthalene ug/L	2-Methyl-naphthalene ug/L	Naphthalene ug/L	Phenanthrene ug/L	Pyrene ug/L
gp#1	7/25/97	261005	N.D.	0.040 Q	0.037 Q	0.044	0.071	0.022 Q	0.055	0.039 Q	0.058	N.D.	0.067	N.D.	N.D.	N.D.	0.071 Q	0.076
gp#2	7/25/97	261145	13 Q	N.D.	N.D.	N.D.	N.D.	1.7 Q	43	N.D.	6.6 Q	98	N.D.	1,100	2,200	350	230	51
MWW#1	10/15/98	1389	2,300	N.D.	N.D.	450	N.D.	N.D.	N.D.	N.D.	890.0	N.D.	N.D.	N.D.	230,000	37,000	170,000	1,300
MWW#3	10/15/98	1390	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	0.15	N.D.
MWW#2	10/15/98	1391	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	0.79q	N.D.	15	24	20	5	N.D.
MWW#4	10/15/98	1392	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
WDR Enforcement Standard (ES)			3000*	NA	0.2	0.2* ug/L	NA	NA	0.2*	NA	400*	400	NA	NA	NA	40 ug/L	NA	250*
WDR Preventive Action Limit (PAL)			600*	NA	0.02	0.02* ug/L	NA	NA	0.02*	NA	80*	80	NA	NA	NA	8 ug/L	NA	50*

* recommended standards, not yet codified in NR 140

ug/L: micrograms per liter

NA: not applicable

N.D.: not detected at or above laboratory method detection limit

Q: The parameter has been detected between the limit of detection (LOD) and the limit of quantitation (LOQ).

Bold type indicates that the value is above WDR ES.

