

GIS REGISTRY
Cover Sheet

SEP 16 2011

July, 2008
(RR 5367)

Source Property Information

BRRTS #: 03-41-000055

CLOSURE DATE: Feb 23, 1989

ACTIVITY NAME: Henri's Food Products

FID #: 241342530

PROPERTY ADDRESS: 2620 West Silver Spring Drive

DATCP #:

MUNICIPALITY: Milwaukee

COMM #: 53209422020H

PARCEL ID #: 169-0030-100

*WTM COORDINATES:

WTM COORDINATES REPRESENT:

X: 687104 Y: 296124

Approximate Center Of Contaminant Source

*Coordinates are in
WTM83, NAD83 (1991)

Approximate Source Parcel Center

Please check as appropriate: (BRRTS Action Code)

Contaminated Media:

Groundwater Contamination > ES (236)

Soil Contamination > *RCL or **SSRCL (232)

Contamination in ROW

Contamination in ROW

Off-Source Contamination

Off-Source Contamination

(note: for list of off-source properties
see "Impacted Off-Source Property")

(note: for list of off-source properties
see "Impacted Off-Source Property")

Land Use Controls:

Soil: maintain industrial zoning (220)

Cover or Barrier (222)

(note: soil contamination concentrations
between residential and industrial levels)

(note: maintenance plan for
groundwater or direct contact)

Structural Impediment (224)

Vapor Mitigation (226)

Site Specific Condition (228)

Maintain Liability Exemption (230)

(note: local government or economic
development corporation)

Monitoring wells properly abandoned? (234)

Yes No N/A

* Residual Contaminant Level

** Site Specific Residual Contaminant Level

BRRTS #: 03-41-000055

ACTIVITY NAME: Former Henri's Food Products

MAPS (continued)

- Geologic Cross-Section Map:** A map showing the source location and vertical extent of residual soil contamination exceeding a Residual Contaminant Level (RCL) or a Site Specific Residual Contaminant Level (SSRCL). If groundwater contamination exceeds a ch. NR 140 Enforcement Standard (ES) when closure is requested, show the source location and vertical extent, water table and piezometric elevations, and locations and elevations of geologic units, bedrock and confining units, if any.

Figure #: Title:

Figure #: Title:

- Groundwater Isoconcentration Map:** For sites closing with residual groundwater contamination, this map shows the horizontal extent of all groundwater contamination exceeding a ch. NR140 Preventive Action Limit (PAL) and an Enforcement Standard (ES). Indicate the direction and date of groundwater flow, based on the most recent sampling data.

Note: This is intended to show the total area of contaminated groundwater.

Figure #: Title:

- Groundwater Flow Direction Map:** A map that represents groundwater movement at the site. If the flow direction varies by more than 20° over the history of the site, submit 2 groundwater flow maps showing the maximum variation in flow direction.

Figure #: Title:

Figure #: Title:

TABLES (meeting the requirements of s. NR 716.15(2)(h)(3))

Tables must be no larger than 11 x 17 inches unless the table is submitted electronically. Tables must not contain shading and/or cross-hatching. The use of **BOLD** or *ITALICS* is acceptable.

- Soil Analytical Table:** A table showing remaining soil contamination with analytical results and collection dates.
Note: This is one table of results for the contaminants of concern. Contaminants of concern are those that were found during the site investigation, that remain after remediation. It may be necessary to create a new table to meet this requirement.

Table #: 1 Title: Analytical Results - Soil Samples

- Groundwater Analytical Table:** Table(s) that show the most recent analytical results and collection dates, for all monitoring wells and any potable wells for which samples have been collected.

Table #: Title:

- Water Level Elevations:** Table(s) that show the previous four (at minimum) water level elevation measurements/dates from all monitoring wells. If present, free product is to be noted on the table.

Table #: Title:

IMPROPERLY ABANDONED MONITORING WELLS

For each monitoring well not properly abandoned according to requirements of s. NR 141.25 include the following documents.
Note: If the site is being listed on the GIS Registry for only an improperly abandoned monitoring well you will only need to submit the documents in this section for the GIS Registry Packet.

- Not Applicable**

- Site Location Map:** A map showing all surveyed monitoring wells with specific identification of the monitoring wells which have not been properly abandoned.

Note: If the applicable monitoring wells are distinctly identified on the Detailed Site Map this Site Location Map is not needed.

Figure #: Title:

- Well Construction Report:** Form 4440-113A for the applicable monitoring wells.

- Deed:** The most recent deed as well as legal descriptions for each property where a monitoring well was not properly abandoned.

- Notification Letter:** Copy of the notification letter to the affected property owner(s).

BRRTS #: 03-41-000055

ACTIVITY NAME: Former Henri's Food Products

NOTIFICATIONS

Source Property

Not Applicable

Letter To Current Source Property Owner: If the source property is owned by someone other than the person who is applying for case closure, include a copy of the letter notifying the current owner of the source property that case closure has been requested.

Return Receipt/Signature Confirmation: Written proof of date on which confirmation was received for notifying current source property owner.

Off-Source Property

Group the following information per individual property and label each group according to alphabetic listing on the "Impacted Off-Source Property" attachment.

Not Applicable

Letter To "Off-Source" Property Owners: Copies of all letters sent by the Responsible Party (RP) to owners of properties with groundwater exceeding an Enforcement Standard (ES), and to owners of properties that will be affected by a land use control under s. 292.12, Wis. Stats.

Note: Letters sent to off-source properties regarding residual contamination must contain standard provisions in Appendix A of ch. NR 726.

Number of "Off-Source" Letters:

Return Receipt/Signature Confirmation: Written proof of date on which confirmation was received for notifying any off-source property owner.

Deed of "Off-Source" Property: The most recent deed(s) as well as legal descriptions, for all affected deeded **off-source** property(ies). This does not apply to right-of-ways.

Note: If a property has been purchased with a land contract and the purchaser has not yet received a deed, a copy of the land contract which includes the legal description shall be submitted instead of the most recent deed. If the property has been inherited, written documentation of the property transfer should be submitted along with the most recent deed.

Letter To "Governmental Unit/Right-Of-Way" Owners: Copies of all letters sent by the Responsible Party (RP) to a city, village, municipality, state agency or any other entity responsible for maintenance of a public street, highway, or railroad right-of-way, within or partially within the contaminated area, for contamination exceeding a groundwater Enforcement Standard (ES) and/or soil exceeding a Residual Contaminant Level (RCL) or a Site Specific Residual Contaminant Level (SSRCL).

Number of "Governmental Unit/Right-Of-Way Owner" Letters:



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Carroll D. Besadny
Secretary

Box 12436
Milwaukee, Wisconsin 53212
Fax: (414) 562-1258

February 23, 1989

File Ref: 4440

Mr. Joseph Plunkett
Henri's Food Product Co., Inc.
2730 West Silver Spring Drive
Milwaukee, WI 53209

FIA 241342530
Bret's 03-41-060055

2620 JH 5/21/83

Dear Mr. Plunkett:

RE: Site remediation at (2730) West Silver Spring Drive, Milwaukee.

This is to acknowledge the receipt of your letter dated February 8, 1989 in regard to the above referenced site. Thank you for your detailed response and update.

Our records also indicated that Mr. Jim Schmidt of this Department had talked to you on September 30, 1988 and recommended the placement of the vapor well. But because this office received no written confirmation from you that the recommendation had been implemented, your file was kept active. Based on the data supplied in the February 8 letter and that previously on record, it appears that remediation work is adequate. With the recommendation of Jim Schmidt, the Department concludes no further action will be required of you at this time. If problems arise in the future, however, further investigation may be necessary. Please bear in mind that another test of the well vapors may be required in the future.

If you have any questions feel free to contact me at (414) 562-9693. Thank you for the responsible manner in which your company has handled the clean up.

Sincerely,

A. Thomas Honeyager
Environmental Repair Specialist

ATH/pan

c: Tom Bergamini, ERR-SW/3
✓SED Case File

CAP MAINTENANCE PLAN

August 25, 2011

Property Located at:

2620 West Silver Spring Drive
Milwaukee, Wisconsin 53209

FID No. 241342530
BRRTS No. 03-41-000055

Described as follows:

2620 West Silver Spring Drive
Tax Key # 169-0030-100
As described on the attached Exhibit A

Introduction:

This document is the Maintenance Plan for a cap at the above-referenced property (the "Property") in accordance with the requirements of s. NR 724.13(2), Wisconsin Administrative Code. The maintenance activities relate to the existing cap within specific areas of the Property.

More site-specific information about the Property may be found in:

- The case file in the Wisconsin Department of Natural Resources (DNR) southeast regional office.
- BRRTS on the Web (DNR's internet based data base of contaminated sites): <http://botw.dnr.state.wi.us/botw/SetUpBasicSearchForm.do>
- GIS Registry PDF file for further information on the nature and extent of contamination: <http://dnrmapping.wisconsin.gov/imf/imf.jsp?site=brrts2> and
- The DNR project manager (contact information found on the last page).

Description of Residual Impacts:

The property is zoned for commercial use and the zoning is consistent with the current and planned future use. Site investigation (SI) activities have been conducted and the results of SI activities at the Property indicate that soils impacted with petroleum are present southwest of the building on the Property within the top four feet at levels that are above DNR direct contact standards. The area of residual soil impacts is currently covered by a concrete and/or asphalt paved parking lot, which is acting as a Cap for direct contact at the Property. The maintenance activities relate to the existing concrete and/or asphalt paved parking lot occupying an area over the contaminated soils on site. The location of the ground surface to be maintained in accordance with this Plan and the extent of residually impacted soil required to be capped is identified on the attached Figure 1 ("Exhibit B").

Description of the Cap to be maintained:

The concrete/asphalt paved areas (these features combined construe the "Cap") that exist over residual soil impacts on the above-described property in the locations shown on the attached Figure 1 ("Exhibit B") serve as a barrier to prevent direct human contact with residual soil that might

otherwise pose a threat to human health. Based on the current and future use of the Property, the Cap should function as intended unless disturbed.

Annual Inspection:

The Cap overlying residual soil impacts and as depicted on the attached Figure 1 ("Exhibit B") will be inspected once a year, normally in the spring after all snow and ice is gone, for deterioration, cracks and other potential problems that can cause exposure to underlying soils. The inspections will be performed by the Property owner or their designated representative. The inspections will be performed to evaluate damage due to settling, exposure to the weather, wear from traffic, increasing age, and other factors. Any area where soils have become or are likely to become exposed will be documented. A log of the inspections and any repairs will be maintained by the Property owner and is included as Exhibit C, "Cap Inspection Log." The inspection log will include recommendations for necessary repair of any areas of the Cap where underlying soils are exposed. Once repairs are completed, they will be documented in the inspection log. A copy of the inspection log will be kept at the address of the Property owner and available for submittal or inspection by DNR representatives upon their request.

Maintenance Activities:

If problems are noted during the annual inspections or at any other time during the year, repairs will be scheduled as soon as practical. Repairs can include patching and filling or larger resurfacing or construction operations. In the event that necessary maintenance activities expose the underlying soil, the Property owner must inform maintenance workers of the direct contact exposure hazard and provide them with appropriate personal protection equipment (PPE). The Property owner must also sample any soil that is excavated from the capped area of the Property prior to disposal to ascertain if soil impacts remain. The soil must be treated, stored, and disposed of by the Property owner in accordance with applicable local, state, and federal law.

In the event that the Cap overlying the residual soil impacts is removed or replaced, the replacement barrier must be equivalent for the purpose of minimizing direct contact with the underlying soil. Any replacement barrier will be subject to the same maintenance and inspection guidelines as outlined in this Cap Maintenance Plan unless indicated otherwise by the DNR or its successor.

The Property owner, in order to maintain the integrity of the Cap, will maintain a copy of this Cap Maintenance Plan at the office of the property owner and make it available to all interested parties (i.e. on-site employees, contractors, future Property owners, etc.) for viewing.

Prohibition of Activities and Notification of DNR Prior to Actions Affecting the Cap:

The following activities are prohibited on any portion of the Property where the Cap is required as shown on Exhibit B, unless prior written approval has been obtained from the DNR: (1) permanent removal of the existing cap; (2) replacement of the cap with another type of barrier; (3) excavating or grading of the land surface; (4) filling on the capped surface; (5) plowing for agricultural cultivation; and (6) construction or placement of a building or other structure within the capped area.


Amendment or Withdrawal of Maintenance Plan:

This Maintenance Plan can be amended or withdrawn by the Property owner and its successors with the written approval of DNR.

Contact Information (as of August 20, 2011):

Property Owner: 2620 Silver Spring, LLC
Ms. Annette Tipton
2620 West Silver Spring Drive
Milwaukee, WI 53209
(414) 536-5800

Signature: _____



Ms. Annette Tipton
President

Consultant: Environmental & Development Solutions, Inc.
Attn: Richard Frieeseke, P.E.
6637 N. Sidney Place
Milwaukee, WI 53209
(414) 228-9810

DNR: Mr. John Hnat
Hydrogeologist
Wisconsin Department of Natural Resources
2300 N. Dr. Martin Luther King Jr. Drive
Milwaukee, WI 53212
(414) 263-8644

EXHIBIT B

5618

5625

Alley

N. 27th Street

Grass

Sidewalk

Asphalt

P-1

fmr. UST cavity

Capped Area



fmr. dispenser islands

Asphalt

approximate property boundary

Sidewalk

Subject Property
2620 W.
Silver Spring

P-4

P-5

| | |
|-------------|---------|
| P-2: 2-4 FT | |
| PVOC+ Naph | 7-22-10 |
| EB | 59,000 |
| Xylenes | 12,320 |



2608

2602

W. Silver Spring Drive

KEY

- = Phase II probehole location
- E = Ethylbenzene
- N = Naphthalene
- X = Total xylenes
- ~ = Cap



File No.: 100603d
 DWG Date: 7-23-10
 Rev Date: 8-22-2011
 Drawn By: TJO
 Checked By (PM): MJR

Cap Maintenance Plan Diagram
 2620 W. Silver Spring Drive Property
 Milwaukee, Wisconsin

Figure

1

State Bar of Wisconsin Form 6-2003
SPECIAL WARRANTY DEED

Document Number

Document Name

THIS DEED, made between HPM ENTERPRISES, INC., a Wisconsin corporation
(“Grantor,” whether one or more), and
2620 SILVER SPRING LLC, a Wisconsin limited liability company
(“Grantee,” whether one or more).

Grantor, for a valuable consideration, conveys to Grantee the following described real estate, together with the rents, profits, fixtures and other appurtenant interests, in Milwaukee County, State of Wisconsin (“Property”) (if more space is needed, please attach addendum):

Lots 20, 21, 22 and 23 in Block 3, in Crestwood, being a Subdivision of a part of the South 1/2 of Section 30, Town 8 North, Range 22 East, and the Southeast 1/4 of Section 25, Town 8 North, Range 21 East, in the City of Milwaukee, County of Milwaukee, State of Wisconsin.

Recording Area

Name and Return Address

DEWITT ROSS + STEVENS
SHAWN GOVERN
13835 BISHOPS DR # 300
BROOKFIELD WI 53005

169-0030-100-X

Parcel Identification Number (PIN)

This is not homestead property.
(is) (is not)

Grantor warrants that the title to the Property is good, indefeasible, in fee simple and free and clear of encumbrances arising by, through, or under Grantor, except municipal and zoning ordinances and agreements entered under them, recorded easements for the distribution of utility and municipal services, recorded building and use restrictions and covenants, and general taxes levied in the year of closing.

Dated August 20, 2010

HPM ENTERPRISES, INC.

(SEAL) By: Steven Mahler (SEAL)
* Steven Mahler, President

(SEAL) _____ (SEAL)

AUTHENTICATION

Signature(s) _____

authenticated on _____

TITLE: MEMBER STATE BAR OF WISCONSIN

(If not, _____
authorized by Wis. Stat. § 706.06)

THIS INSTRUMENT DRAFTED BY:

Mary Neese Fertl, Esq.

ACKNOWLEDGMENT

STATE OF WISCONSIN)
WAUKESHA COUNTY) ss.

Personally came before me on AUGUST 20, 2010
the above named STEVEN MAHLER

to me known to be the person(s) who executed the foregoing instrument and acknowledge the same.

Michele Schmid
Notary Public, State of Wisconsin
Commission (is permanent) (expires: 9-16-12)



(Signatures may be authenticated or acknowledged. Both are not necessary.)

NOTE: THIS IS A STANDARD FORM.
SPECIAL WARRANTY DEED

TO THIS FORM SHOULD BE CLEARLY IDENTIFIED.

FORM NO. 6-2003

ALTA/ACSM LAND TITLE SURVEY


Glendale
2620 WEST SILVER SPRING DRIVE, CITY OF MILWAUKEE, WISCONSIN.

PARCEL III:
LOTS TWENTY (20), TWENTY-ONE (21), TWENTY-TWO (22) AND TWENTY-THREE (23) IN BLOCK THREE (3) IN CRESTWOOD,
BEING A SUBDIVISION OF PART OF THE SOUTHEAST ONE-QUARTER (1/4) OF SECTION TWENTY-FIVE (25), IN TOWNSHIP
EIGHT (8) NORTH, RANGE TWENTY-ONE (21) EAST, AND A PART OF THE SOUTH ONE-HALF (1/2) OF SECTION THIRTY (30),
IN TOWNSHIP EIGHT (8) NORTH, RANGE TWENTY-TWO (22) EAST, IN THE CITY OF MILWAUKEE, COUNTY OF
MILWAUKEE, STATE OF WISCONSIN.

FEBRUARY 8, 1999

PAK TECHNOLOGIES

SURVEY NO. 158737-MS



VICINITY SKETCH



NOTES:

- BEARINGS ARE BASED ON THE WEST LINE OF THE SOUTHWEST 1/4 OF SECTION 30, TOWNSHIP 8 NORTH, RANGE 22 EAST, WHICH IS ASSUMED TO BEAR NORTH 00°08'00" WEST
- THIS SURVEY WAS PREPARED BASED ON WISCONSIN TITLE SERVICE COMPANY, INC., ISSUING AGENT FOR FIRST AMERICAN TITLE INSURANCE COMPANY TITLE COMMITMENT NO. 308307, EFFECTIVE DATE OF NOVEMBER 11, 1998, WHICH LISTS THE FOLLOWING EASEMENTS AND/OR RESTRICTIONS:
 - A. UTILITY EASEMENT RECORDED ON OCTOBER 19, 1926 IN VOLUME 1161 OF DEEDS AT PAGE 535. AS DOCUMENT NO. 1471429. SHOWN
- ACCORDING TO FLOOD INSURANCE RATE MAP OF THE CITY OF MILWAUKEE, COMMUNITY PANEL NO. 550278 0011 C, EFFECTIVE DATE OF NOVEMBER 15, 1985, THIS SITE FALLS IN ZONE (C) AREAS OF MINIMAL FLOODING
- THERE ARE 47 REGULAR PARKING SPACES AND 1 HANDICAPPED SPACE MARKED ON THIS SITE
- THE BASIC ZONING INFORMATION LISTED BELOW IS TAKEN FROM MUNICIPAL CODES AND DOES NOT REFLECT ALL REGULATIONS THAT MAY APPLY - SITE IS ZONED L/C/40 (LOCAL BUSINESS DISTRICT)
 - FRONT SETBACK - AVERAGE OR 20' MAX.
 - SIDEYARD SETBACK - 0'
 - REARYARD SETBACK - 0'
 - MAXIMUM HEIGHT - 40'

TO: PAK TECHNOLOGIES,
BESTFOODS,
JOHNSON BANK, ITS SUCCESSORS AND/OR ASSIGNS, AND
FIRST AMERICAN TITLE INSURANCE COMPANY

THIS IS TO CERTIFY THAT THIS MAP OR PLAT AND THE SURVEY ON WHICH IT IS BASED WERE MADE (i) IN ACCORDANCE WITH "MINIMUM STANDARD DETAIL REQUIREMENTS FOR ALTA/ACSM LAND TITLE SURVEYS," JOINTLY ESTABLISHED AND ADOPTED BY ALTA, ACSM AND NSPS IN 1997 AND INCLUDES ITEMS 1, 2, 3, 4, 6, 7A, 7B, 7C, 8, 9, 10, 11A AND 13 OF TABLE "A" THEREOF, AND (ii) PURSUANT TO THE ACCURACY STANDARDS (AS ADOPTED BY ALTA AND ACSM AND IN EFFECT ON THE DATE OF THIS CERTIFICATION) OF AN URBAN SURVEY, AND IS CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF.

FEBRUARY 8, 1999



AREA-20,434 SQ.FT.
0.4691 AC.

PARCEL-III

ASPHALT

LOT-20

LOT-21

LOT-22

LOT-23

W. SILVER SPRING DR. 120FT.

(PUBLIC RIGHT OF WAY)

100 FT. ST.

(PUBLIC RIGHT OF WAY)

N. 27TH.

WEST LINE OF SW 1/4 SEC. 10 N. 00° 08' 00" W

SCALE: 1" = 20'

National Survey & Engineering

Telephone 414-781-1000
Facsimile 414-781-8466
16745 W. Bluemound Road
Suite 200
Brookfield, WI 53005-5938
www.nsa.com



August 23, 2011

Program Assistant
Remediation & Redevelopment Program
Wisconsin Department of Natural Resources
2300 N. Dr. Martin Luther King Jr. Dr.
Milwaukee, WI 53212

RE: GIS Registry for the Former Henri's Food Products Property Located at
2620 West Silver Spring Drive in Milwaukee, Wisconsin — EDS Project #
100603, DNR BRRTS # 03-41-000055, FID # 241342530, Commerce #
53209-4220-20


Dear Program Assistant:

The property is located at 2620 West Silver Spring Drive in Milwaukee, Wisconsin. I have provided the necessary information for placement of the property on the DNR's soil GIS registry. To the best of my knowledge, I believe that the legal descriptions attached to this statement are complete and accurate.

Respectfully,




Ms. Annette Tipton
President
2620 Silver Spring, LLC




| | | |
|---|--|--|
| <p>Approximate Scale</p> <p>1" = 1,565'</p> | <p>United States Geological Survey Topographic Map Milwaukee Quadrangle</p> <p>SW 1/4 of SW 1/4 of Sec 30, T8N, R22E</p> | |
|---|--|--|

| | | |
|--|--|---------------------|
| | <p>Vicinity Diagram 2620 West Silver Spring Drive Property Milwaukee, Wisconsin</p> | <p>Figure 1</p> |
|--|--|---------------------|




KEY
 ● = Phase II probehole location



File No.: 100603b
 DWG Date: 7-23-10
 Rev Date: 8-22-2011
 Drawn By: JEB
 Checked By (PM): MJR


Site Features Diagram
 2620 W. Silver Spring Drive Property
 Milwaukee, Wisconsin

Figure
 2




KEY

- = Phase II probehole location
- E = Ethylbenzene
- N = Naphthalene
- X = Total xylenes
- ~ = RCL exceedance contour



Notes: All concentrations presented in parts per billion (ppb).
 Concentrations in blue exceed their NR 720 generic RCLs.
 Concentrations in red exceed their NR 746 Table 1 values.



| |
|----------------------|
| File No.: 100603c |
| DWG Date: 7-23-10 |
| Rev Date: 8-22-2011 |
| Drawn By: TJO |
| Checked By (PM): MJR |

Soil GIS Diagram
 2620 W. Silver Spring Drive Property
 Milwaukee, Wisconsin

Table 1
Analytical Results - Soil Samples
2620 West Silver Spring Drive Property
Milwaukee, Wisconsin

| Sample Location | Sampling Date | Lead (ppm) | DRO (ppm) | GRO (ppm) | Benzene (ppb) | Ethyl-benzene (ppb) | Methyl tert-butyl ether (ppb) | Naphthalene (ppb) | Toluene (ppb) | Combined TMBs (ppb) | Total Xylenes (ppb) |
|--------------------|---------------|------------|------------|--------------|---------------|---------------------|-------------------------------|-------------------|---------------|---------------------|---------------------|
| P-1: 6-8 FT | 7/22/2010 | NA | NA | <2.90 | <25.0 | <25.0 | <25.0 | NA | <25.0 | <50.0 | <75.0 |
| P-2: 2-4 FT | 7/22/2010 | 22.7 | NA | <i>1,680</i> | <250 | 59,000 | <250 | NA | <250 | 17,260 | <i>12,320</i> |
| P-2: 6-8 FT | 7/22/2010 | NA | NA | <3.00 | <25.0 | <25.0 | <25.0 | NA | <25.0 | <50.0 | <75.0 |
| P-3:2-4 FT | 7/22/2010 | NA | NA | 30.5 | <25.0 | 48.3 | <25.0 | NA | <25.0 | 146 | 126 |
| P-4:4-6 FT | 7/22/2010 | NA | <0.95 | NA | <25.0 | <25.0 | <25.0 | NA | <25.0 | <50.0 | <75.0 |
| P-5:7-8 FT | 8/4/2011 | NA | NA | NA | <62.5 | <62.5 | <62.5 | <i>2,000</i> | <62.5 | 609 | <200 |
| NR 720 Generic RCL | | <i>50</i> | <i>250</i> | <i>250</i> | <i>5.5</i> | <i>2,900</i> | <i>NS</i> | <i>400</i> | <i>1,500</i> | <i>NS</i> | <i>4,100</i> |
| NR 746 Table 1 | | <i>NS</i> | <i>NS</i> | <i>NS</i> | <i>8,500</i> | <i>4,600</i> | <i>NS</i> | <i>2,700</i> | <i>38,000</i> | <i>83K/11K</i> | <i>42,000</i> |

Note: Concentrations in *blue italics* exceed their respective generic RCL.

Note: Concentrations in **red bold** exceed their respective Table 1 value.

Environmental & Development Solutions, Inc.
Guide to Abbreviations
in Laboratory Data Tables

< = Less than the specified detection limit.

DO = Dissolved Oxygen

ES = Enforcement Standard

DRO = Diesel range organics

GRO = Gasoline range organics

iu = instrument units

MTBE = Methyl-tert butyl ether

mV = Millivolts

NA = Not analyzed for indicated parameter

NM = Not measured for indicated parameter

NR = No recovery at this interval.

NR 140 ES = Wisconsin Administrative Code NR 140 Groundwater Quality
Enforcement Standard

NR 140 PAL = Wisconsin Administrative Code NR 140 Groundwater Quality
Preventive Action Limit

NS = No NR 140 ES/PAL or NR 720 RCL standard has been established.

ORP = Oxidation-reduction potential

PAL = Preventive Action Limit

PID = Photoionization detector

ppb = parts per billion

ppm = parts per million

RCL = Residual contaminant level as established in WAC Chapter NR 720

TMBs = Trimethylbenzenes (combined 1,2,4- and 1,3,5-trimethylbenzene)

umhos = Micromhos