

GIS REGISTRY

Cover Sheet

May, 2008
(RR 5367)

Source Property Information

BRRTS #: 03-65-192121

CLOSURE DATE: Feb 2, 2010

ACTIVITY NAME: Speedway SuperAmerica Store #2067

FID #: 265091420

PROPERTY ADDRESS: 499 W. Main St.

DATCP #:

MUNICIPALITY: Lake Geneva

COMM #: 53147198099

PARCEL ID #: ZOP 000302

*WTM COORDINATES:

X: 648786 Y: 236686

** Coordinates are in
WTM83, NAD83 (1991)*

WTM COORDINATES REPRESENT:

Approximate Center Of Contaminant Source

Approximate Source Parcel Center

Please check as appropriate: (BRRTS Action Code)

Contaminated Media:

Groundwater Contamination > ES (236)

Contamination in ROW

Off-Source Contamination

*(note: for list of off-source properties
see "Impacted Off-Source Property")*

Soil Contamination > *RCL or **SSRCL
or Direct Contact > 4 ft (232)

Contamination in ROW

Off-Source Contamination

*(note: for list of off-source properties
see "Impacted Off-Source Property")*

Land Use Controls:

Soil: maintain industrial zoning (220)

*(note: soil contamination concentrations
between residential and industrial levels)*

Structural Impediment (224)

Site Specific Condition (228)

Cover or Barrier (222)

*(note: maintenance plan for
groundwater or direct contact)*

Vapor Mitigation (226)

Maintain Liability Exemption (230)

*(note: local government or economic
development corporation)*

Monitoring wells properly abandoned? (234)

Yes No

* Residual Contaminant Level

** Site Specific Residual Contaminant Level

This Adobe Fillable form is intended to provide a list of information that is required for evaluation for case closure. It is to be used in conjunction with Form 4400-202, Case Closure Request. The closure of a case means that the Department has determined that no further response is required at that time based on the information that has been submitted to the Department.

NOTICE: Completion of this form is mandatory for applications for case closure pursuant to ch. 292, Wis. Stats. and ch. NR 726, Wis. Adm. Code, including cases closed under ch. NR 746 and ch. NR 726. The Department will not consider, or act upon your application, unless all applicable sections are completed on this form and the closure fee and any other applicable fees, required under ch. NR 749, Wis. Adm. Code, Table 1 are included. It is not the Department's intention to use any personally identifiable information from this form for any purpose other than reviewing closure requests and determining the need for additional response action. The Department may provide this information to requesters as required by Wisconsin's Open Records law [ss. 19.31 - 19.39, Wis. Stats.].

BRRTS #: 03-65-192121 PARCEL ID #: ZOP 00302

ACTIVITY NAME: Speedway 2067 WTM COORDINATES: X: 648786 Y: 236686

CLOSURE DOCUMENTS (the Department adds these items to the final GIS packet for posting on the Registry)

- Closure Letter**
- Maintenance Plan** (if activity is closed with a land use limitation or condition (land use control) under s. 292.12, Wis. Stats.)
- Conditional Closure Letter**
- Certificate of Completion (COC)** for VPLE sites

SOURCE LEGAL DOCUMENTS

- Deed:** The most recent deed as well as legal descriptions, for the **Source Property** (where the contamination originated). Deeds for other, off-source (off-site) properties are located in the **Notification** section.
Note: If a property has been purchased with a land contract and the purchaser has not yet received a deed, a copy of the land contract which includes the legal description shall be submitted instead of the most recent deed. If the property has been inherited, written documentation of the property transfer should be submitted along with the most recent deed.
- Certified Survey Map:** A copy of the certified survey map or the relevant section of the recorded plat map for those properties where the legal description in the most recent deed refers to a certified survey map or a recorded plat map. (lots on subdivided or platted property (e.g. lot 2 of xyz subdivision)).
Figure #: **Title:**
- Signed Statement:** A statement signed by the Responsible Party (RP), which states that he or she believes that the attached legal description accurately describes the correct contaminated property.

MAPS (meeting the visual aid requirements of s. NR 716.15(2)(h))

Maps must be no larger than 8.5 x 14 inches unless the map is submitted electronically.

- Location Map:** A map outlining all properties within the contaminated site boundaries on a U.S.G.S. topographic map or plat map in sufficient detail to permit easy location of all parcels. If groundwater standards are exceeded, include the location of all potable wells within 1200 feet of the site.
Note: Due to security reasons municipal wells are not identified on GIS Packet maps. However, the locations of these municipal wells must be identified on Case Closure Request maps.
Figure #: 1 Title: General Site Location
- Detailed Site Map:** A map that shows all relevant features (buildings, roads, individual property boundaries, contaminant sources, utility lines, monitoring wells and potable wells) within the contaminated area. This map is to show the location of all contaminated public streets, and highway and railroad rights-of-way in relation to the source property and in relation to the boundaries of groundwater contamination exceeding a ch. NR 140 Enforcement Standard (ES), and/or in relation to the boundaries of soil contamination exceeding a Residual Contaminant Level (RCL) or a Site Specific Residual Contaminant Levels (SSRCL) as determined under s. NR 720.09, 720.11 and 720.19.
Figure #: 2 Title: Site layout
- Soil Contamination Contour Map:** For sites closing with residual soil contamination, this map is to show the location of all contaminated soil and a single contour showing the horizontal extent of each area of contiguous residual soil contamination that exceeds a Residual Contaminant Level (RCL) or a Site Specific Residual Contaminant Level (SSRCL) as determined under s. NR 720.09, 720.11 and 720.19.
Figure #: 1 Title: Soil Quality Map

BRRTS #: 03-65-192121

ACTIVITY NAME: Speedway 2067

MAPS (continued)

Geologic Cross-Section Map: A map showing the source location and vertical extent of residual soil contamination exceeding a Residual Contaminant Level (RCL) or a Site Specific Residual Contaminant Level (SSRCL). If groundwater contamination exceeds a ch. NR 140 Enforcement Standard (ES) when closure is requested, show the source location and vertical extent, water table and piezometric elevations, and locations and elevations of geologic units, bedrock and confining units, if any.

Figure #: Title:

Figure #: Title:

Groundwater Isoconcentration Map: For sites closing with residual groundwater contamination, this map shows the horizontal extent of all groundwater contamination exceeding a ch. NR140 Preventive Action Limit (PAL) and an Enforcement Standard (ES). Indicate the direction and date of groundwater flow, based on the most recent sampling data.

Note: This is intended to show the total area of contaminated groundwater.

Figure #: 3 Title: Groundwater Analytical Data Map, March 30, 2009

Groundwater Flow Direction Map: A map that represents groundwater movement at the site. If the flow direction varies by more than 20° over the history of the site, submit 2 groundwater flow maps showing the maximum variation in flow direction.

Figure #: 3 Title: Groundwater Flow Map 2/3/2006

Figure #: Title:

TABLES (meeting the requirements of s. NR 716.15(2)(h)(3))

Tables must be no larger than 8.5 x 14 inches unless the table is submitted electronically. Tables must not contain shading and/or cross-hatching. The use of **BOLD** or *ITALICS* is acceptable.

Soil Analytical Table: A table showing remaining soil contamination with analytical results and collection dates.

Note: This is one table of results for the contaminants of concern. Contaminants of concern are those that were found during the site investigation, that remain after remediation. It may be necessary to create a new table to meet this requirement.

Table #: 1 Title: Soil Analytical Results

Groundwater Analytical Table: Table(s) that show the most recent analytical results and collection dates, for all monitoring wells and any potable wells for which samples have been collected.

Table #: 2 Title: Groundwater Analytical Results

Water Level Elevations: Table(s) that show the previous four (at minimum) water level elevation measurements/dates from all monitoring wells. If present, free product is to be noted on the table.

Table #: 2 Title: Groundwater Analytical Results

IMPROPERLY ABANDONED MONITORING WELLS

For each monitoring well not properly abandoned according to requirements of s. NR 141.25 include the following documents.

Note: If the site is being listed on the GIS Registry for only an improperly abandoned monitoring well you will only need to submit the documents in this section for the GIS Registry Packet.

Not Applicable

Site Location Map: A map showing all surveyed monitoring wells with specific identification of the monitoring wells which have not been properly abandoned.

Note: If the applicable monitoring wells are distinctly identified on the Detailed Site Map this Site Location Map is not needed.

Figure #: Title:

Well Construction Report: Form 4440-113A for the applicable monitoring wells.

Deed: The most recent deed as well as legal descriptions for each property where a monitoring well was not properly abandoned.

Notification Letter: Copy of the notification letter to the affected property owner(s).

BRRTS #: 03-65-192121

ACTIVITY NAME: Speedway 2067

NOTIFICATIONS


Source Property

- Letter To Current Source Property Owner:** If the source property is owned by someone other than the person who is applying for case closure, include a copy of the letter notifying the current owner of the source property that case closure has been requested.
- Return Receipt/Signature Confirmation:** Written proof of date on which confirmation was received for notifying current source property owner.

Off-Source Property

Group the following information per individual property and label each group according to alphabetic listing on the "Impacted Off-Source Property" attachment.

- Letter To "Off-Source" Property Owners:** Copies of all letters sent by the Responsible Party (RP) to owners of properties with groundwater exceeding an Enforcement Standard (ES), and to owners of properties that will be affected by a land use control under s. 292.12, Wis. Stats.
Note: Letters sent to off-source properties regarding residual contamination must contain standard provisions in Appendix A of ch. NR 726.
- Number of "Off-Source" Letters:**
- Return Receipt/Signature Confirmation:** Written proof of date on which confirmation was received for notifying any off-source property owner.
- Deed of "Off-Source" Property:** The most recent deed(s) as well as legal descriptions, for all affected deeded **off-source property(ies)**. This does not apply to right-of-ways.
Note: If a property has been purchased with a land contract and the purchaser has not yet received a deed, a copy of the land contract which includes the legal description shall be submitted instead of the most recent deed. If the property has been inherited, written documentation of the property transfer should be submitted along with the most recent deed.
- Letter To "Governmental Unit/Right-Of-Way" Owners:** Copies of all letters sent by the Responsible Party (RP) to a city, village, municipality, state agency or any other entity responsible for maintenance of a public street, highway, or railroad right-of-way, within or partially within the contaminated area, for contamination exceeding a groundwater Enforcement Standard (ES) and/or soil exceeding a Residual Contaminant Level (RCL) or a Site Specific Residual Contaminant Level (SSRCL).
- Number of "Governmental Unit/Right-Of-Way Owner" Letters:**



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Jim Doyle, Governor
Scott Hassett, Secretary
Gloria L. McCutcheon, Regional Director

Waukesha Service Center
141 NW Barstow Street, Room 180
Waukesha, Wisconsin 53188
Telephone 262-574-2100
FAX 262-574-2117

February 2, 2010

Mr. Michael G. Musselman
Speedway SuperAmerica, LLC
P.O. Box 1500
Springfield, OH 45501

Subject: Final Case Closure with Continuing Obligations
Speedway SuperAmerica Store #2067, 499 W. Main St., Lake Geneva, WI
FID# 265091420 BRRTS# 03-65-192121 Commerce# 53147-1980-99

Dear Mr. Rickabaugh:

On October 6, 2009, the Wisconsin Department of Natural Resources' (the Department) Southeast Region Closure Committee reviewed your request for closure of the case described above. This committee reviews environmental remediation cases for compliance with state laws and standards to maintain consistency in the closure of these cases. On October 9, 2009, you were notified that the Closure Committee had granted conditional closure to this case.

On December 7, 2009, the Department received information or documentation indicating that you have complied with the requirements for final closure. The monitoring well abandonment forms were received demonstrating the monitoring wells that will not be used for the remaining open case (BRRTS# 02-65-554284) were properly abandoned. Also the information requested by the Department for the GIS Registry was submitted.

Based on the correspondence and data provided, it appears that the above referenced leaking underground storage case (BRRTS# 03-65-192121) meets the closure requirements in ch. NR 726, Wisconsin Administrative Code. The Department considers this case closed (BRRTS# 03-65-192121) and no further investigation or remediation is required at this time, however, you and future property owners must comply with certain continuing obligations as explained in this letter.

GIS Registry

This site will be listed on the Remediation and Redevelopment Program's GIS Registry. The specific reasons are summarized below:

- Residual soil contamination exists that must be properly managed should it be excavated or removed

- Pavement, an engineered cover or a soil barrier must be maintained over contaminated soil and the state must approve any changes to this barrier
- Groundwater contamination is present above Chapter NR 140 enforcement standards

This letter and information that was submitted with your closure request application will be included on the GIS Registry. To review the sites on the GIS Registry web page, visit the RR Sites Map page at <http://dnr.wi.gov/org/aw/rr/gis/index.htm>. If the property is listed on the GIS Registry because of remaining contamination and you intend to construct or reconstruct a well, you will need prior Department approval in accordance with s. NR 812.09(4)(w), Wis. Adm. Code. To obtain approval, Form 3300-254 needs to be completed and submitted to the DNR Drinking and Groundwater program's regional water supply specialist. This form can be obtained on-line <http://dnr.wi.gov/org/water/dwg/3300254.pdf> or at the web address listed above for the GIS Registry.

Closure Conditions

Please be aware that pursuant to s. 292.12 Wisconsin Statutes, compliance with the requirements of this letter is a responsibility to which the current property owner and any subsequent property owners must adhere. You must pass on the information about these continuing obligations to the next property owner or owners. If these requirements are not followed or if additional information regarding site conditions indicates that contamination on or from the site poses a threat to public health, safety, welfare, or the environment, the Department may take enforcement action under s. 292.11 Wisconsin Statutes to ensure compliance with the specified requirements, limitations or other conditions related to the property or this case may be reopened pursuant to s. NR 726.09, Wis. Adm. Code. The Department intends to conduct inspections in the future to ensure that the conditions included in this letter including compliance with referenced maintenance plans are met.

Residual Soil Contamination

Residual soil contamination remains at the site in the former dispenser area where the former remedial excavation took place as indicated on the **attached map** and in the information submitted to the Department of Natural Resources. If soil in the specific locations described above is excavated in the future, then pursuant to ch. NR 718 or, if applicable, ch. 289, Stats., and chs. 500 to 536, the property owner at the time of excavation must sample and analyze the excavated soil to determine if residual contamination remains. If sampling confirms that contamination is present the property owner at the time of excavation will need to determine whether the material is considered solid or hazardous waste and ensure that any storage, treatment or disposal is in compliance with applicable standards and rules.

Cover or Barrier

Pursuant to s. 292.12(2)(a), Wis. Stats., the pavement or other impervious cap that currently exists in the location shown on the **attached map** shall be maintained in compliance with the **attached maintenance plan** in order to minimize the infiltration of water and prevent additional groundwater contamination that would violate the groundwater quality standards in ch. NR 140, Wis. Adm. Code, and to prevent direct contact with residual soil contamination that might

otherwise pose a threat to human health. If soil in the specific locations described above is excavated in the future, the property owner at the time of excavation must sample and analyze the excavated soil to determine if residual contamination remains. If sampling confirms that contamination is present the property owner at the time of excavation will need to determine whether the material is considered solid or hazardous waste and ensure that any storage, treatment or disposal is in compliance with applicable statutes and rules.

The **attached maintenance plan and inspection log** are to be kept up-to-date and on-site. Please submit the inspection log to the Department only upon request.

Prohibited Activities

The following activities are prohibited on any portion of the property where pavement is required as shown on the attached map, unless prior written approval has been obtained from the Wisconsin Department of Natural Resources: 1) removal of the existing barrier; 2) replacement with another barrier; 3) excavating or grading of the land surface; 4) filling on capped or paved areas; 5) plowing for agricultural cultivation; 6) construction or placement of a building or other structure.

Residual Groundwater Contamination

Groundwater impacted by benzene contamination greater than enforcement standards set forth in ch. NR140, Wis. Adm. Code, is present on this contaminated property. For more detailed information regarding the locations where groundwater samples have been collected (i.e., monitoring well locations) and the associated contaminant concentrations, refer to the Remediation and Redevelopment Program's GIS Registry at the RR Sites Map page at <http://dnr.wi.gov/org/aw/rr/gis/index.htm>.

Post-Closure Notification Requirements

In accordance with ss, 292.12 and 292.13, Wis. Stats., you must notify the Department before making changes that affect or relate to the conditions of closure in this letter. For this case, examples of changed conditions requiring prior notification include, but are not limited to:

- Disturbance, construction on, change or removal in whole or part of pavement, an engineered cover or a soil barrier that must be maintained over contaminated soil.

Please send written notifications in accordance with the above requirements to Department of Natural Resources, to the attention of Southeast Region RR Program Associate, 2300 North Dr. Martin Luther King Jr. Drive, Milwaukee, WI 53212.

Please be aware that the case may be reopened pursuant to s. NR 726.09, Wis. Adm. Code, if additional information regarding site conditions indicates that contamination on or from the site poses a threat to public health, safety, or welfare or to the environment.

The Department appreciates your efforts to restore the environment at this site. If you have any questions regarding this closure decision or anything outlined in this letter, please contact Dave Volkert at (262) 574-2166.

Sincerely,

Frances M. Koonce

Frances M. Koonce
Remediation & Redevelopment Sub-Team Supervisor

Attachment

- Engineered Cap and Building Barrier Maintenance Plan with Exhibits

cc: Holly Jankovic, Practical Environmental Consultants, Inc.
Shawn Wenzel, Commerce w/o attachments
SER File

CAP MAINTENANCE PLAN

Site:

Former Speedway SuperAmerica Store No. 2067
499 West Main Street
Lake Geneva, Wisconsin 53147

Commerce #53147-1980-99
DNR BRRTS #03-65-19212

Prepared for:

SPEEDWAY SUPERAMERICA LLC

P.O. Box 1500
Springfield, Ohio 45501
Phone: (937) 864-3000
Website: www.ssallc.com

Prepared by:

PRACTICAL ENVIRONMENTAL CONSULTANTS, INC.

1305 Remington Road, Suite A
Schaumburg, Illinois 60173
Phone: (847) 519-3430
Fax: (847) 519-3431
Website: www.pec-inc.com

July 22, 2009



CAP MAINTENANCE PLAN AND INSPECTION LOG

The site is a former Speedway SuperAmerica LLC (SSA) property located at 499 West Main Street in Lake Geneva, Wisconsin. This Cap Maintenance Plan ("Maintenance Plan") has been prepared to provide procedures for the inspection and repair of the existing paved surfaces occupying the area over the soil impacts (collectively identified as the "cap") at the site.

At the time of the Case Closure Request, soil analytical data are above the NR 720 residual contaminant levels (RCLs) and the NR 746 risk screening criteria of the Wisconsin Administrative Code (Wis. Adm. Code). Residual groundwater impacts also remain above the preventative action limits (PALs) and enforcement standards (ESs) contained in NR 140 of the Wis. Adm. Code. Therefore, SSA, the responsible party, is required to submit this Maintenance Plan to the property owner, the City of Lake Geneva, because on-site maintenance activities are necessary to ensure the effectiveness of natural attenuation and to prevent direct human contact with residual soil impacts.

The legal description for the above-referenced property is:

Situated in the City of Lake Geneva, County of Walworth, State of Wisconsin; Commencing at a point in the center line of Main Street in the City of Lake Geneva (formerly Village of Geneva), county and state aforesaid, where the Western line of the Railway not operated by the Chicago & Northwestern Railway Company intersects the center line of Main Street; run thence Northwesterly in the Southwest line of said Railway lands to the center of the outlet of Geneva Lake; thence Southwesterly along the center of said outlet to the center of Main Street; thence East in the center of said Main Street to the place of beginning; excepting the tract described as follows: Commencing at a point in the North line of said Main Street where the Southwesterly line of said Railway Company's right-of-way intersects the said street line; thence Northwesterly in said right-of-way to a pointing the line of the right-of-way first mentioned produced or extended, to the center line of White River; the outlet of Geneva Lake; thence northeasterly in the center line of said White River to the South or Southwest line of the right-of-way of said Railway Company; thence Southeasterly in the line of the right-of-way to a point where the said boundary line of the right-of-way makes a right angle to the Southwest; thence Southwesterly in said right-of-way to the place of the beginning.

The above is the description of record and is subject to valid and subsisting easements and restriction of record.

The maintenance activities relate to the paved surfaces occupying the area over the soil impacts on-site and the groundwater plume. The soil and groundwater is impacted with benzene, toluene, ethylbenzene, and xylenes (BTEX), and methyl tertiary butyl ether (MTBE), vinyl chloride, perchloroethylene (PCE), trichloroethylene (TCE), and cis-1,2- dichloroethylene (DCE). The location of the cap to be maintained in accordance with this Maintenance Plan, as well as the impacted soil and groundwater plumes are identified on the attached map (**Exhibit A**).

Cover Purpose

The cap over the contaminated soil and groundwater plumes serves as a barrier to prevent direct human contact with residual soil contamination that might otherwise pose a threat to human health. This cap also acts as a partial infiltration barrier to minimize future soil-to-groundwater contamination migration that may cause a violation of the groundwater standards in ch. NR 140, Wis. Adm. Code. Based on the current and future use of the property, the cap should function as intended unless disturbed.

Required Annual Inspection

The cap overlying the contaminated soil and groundwater plumes and as depicted in **Exhibit A** will be inspected once a year, normally in the late spring, for deterioration, cracks, and other potential problems that can cause additional infiltration into or allow exposure to underlying soils. The inspections will be performed to evaluate damage due to settling, exposure to the weather, wear from traffic, increasing age, and other factors. Any area where soils have become or are likely to become exposed will be documented. A log of the inspections and any repairs will be maintained by the property owner and is included as **Exhibit B**, Cap Inspection Log. The log will include recommendations for necessary repair of any areas where underlying soils are exposed. Once repairs are completed, they will be documented in the inspection log. A copy of the inspection log should be sent to the Wisconsin Department of Natural Resources (WDNR) at least annually after every inspection, unless otherwise directed in the case closure letter.

Maintenance Activities

If problems are noted during the annual inspections or at any other time during the year, repairs will be scheduled as soon as possible. Repairs can include patching and filling operations or they can include larger resurfacing or construction operations. In the event that necessary maintenance activities expose the underlying soil, the owner must inform maintenance workers of the direct contact exposure hazard and ensure that appropriate personal protection equipment (PPE) is used. The owner must also sample any soil that is excavated from the site prior to disposal to ascertain if contamination remains. The soil must be treated, stored, and disposed of by the owner in accordance with applicable local, state, and federal law.

In the event the cap overlying the impacted soil and groundwater plumes is removed or replaced, the replacement cap must be equally impervious. Any replacement cap will be subject to the same maintenance and inspection guidelines as outlined in this Maintenance Plan unless indicated otherwise by the WDNR or its successor.

The property owner, in order to maintain the integrity of the cap, will maintain a copy of this Maintenance Plan on-site and make it available to all interested parties (e.g., on-site employees, contractors, future property owners) for viewing.

Amendment or Withdrawal of Maintenance Plan

This Maintenance Plan can be amended or withdrawn by the property owner and its successors with the written approval of WDNR.

Contact Information

Site Owner and Operator: The City of Lake Geneva
 Birdell J. Brellenthin, President
 Director of Public Works and Utilities
 361 West Main Street
 Lake Geneva, WI 53147

Consultant: Practical Environmental Consultants, Inc.
 1305 Remington Road – Suite A
 Schaumburg, Illinois 60173
 (847) 519-3430

WDNR: Dave Volkert
 Hydrogeologist
 141 NW Barstow Street, Room 180
 Waukesha, Wisconsin 53188



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Jim Doyle, Governor
Scott Hassett, Secretary
Gloria L. McCutcheon, Regional Director

Waukesha Service Center
141 NW Barstow Street, Room 180
Waukesha, Wisconsin 53188
Telephone 262-574-2100
FAX 262-574-2117

October 9, 2009

Mr. Toby Rickabaugh
Speedway SuperAmerica, LLC
P.O. Box 1500
Springfield, OH 45501

Subject: Conditional Closure Decision
With Requirements to Achieve Final Closure
Speedway SuperAmerica Store #2067, 499 W. Main St., Lake Geneva, WI
FID# 265091420 BRRTS# 03-65-192121 Commerce# 53147-1980-99

Dear Mr. Rickabaugh:

On October 6, 2009, the Wisconsin Department of Natural Resources' (the Department) Southeast Region Closure Committee reviewed your request for closure of the case described above. This committee reviews environmental remediation cases for compliance with state laws and standards to maintain consistency in the closure of these cases.

After careful review of the closure request, the committee has determined that the petroleum contamination on the site from the former underground storage tank system appears to have been investigated and remediated to the extent practicable under site conditions. This leaking underground storage case (BRRTS# 03-65-192121) will be closed when the certain conditions are satisfied; however, the Department is opening an environmental repair case for the chlorinated solvent contamination remaining in the groundwater at the site. The Department is opening a new case because future chlorinated solvent contamination work at the site will not eligible for reimbursement through the Department of Commerce's PECFA program. Please be advised that the Department will be sending a letter under a separate cover notifying you of your legal requirements for investigating and remediating the chlorinated solvent contamination at the site. At the end of this letter, the Department will describe the next steps for taking the chlorinated solvent contamination case to closure.

Based on the correspondence and data provided, the above referenced leaking underground storage case (BRRTS# 03-65-192121) has been remediated to Department standards in accordance with s. NR 726.05, Wis. Adm. Code and will be closed if the following conditions are satisfied:

Monitoring Well Abandonment

Monitoring wells MW-2, MW-6, MW-7 and MW-9 at the site must be properly abandoned in compliance with ch. NR 141, Wis. Adm. Code. Documentation of well abandonment must be submitted to Victoria Stovall on Form 3300-005 found at <http://dnr.wi.gov/org/water/dwg/gw/> or provided by the Department of Natural Resources. **Please do not abandon piezometer PZ1 and monitoring wells MW-1, MW-4, MW-5 and MW-8 because these wells will have to be sampled for the environmental repair case that is to be opened for the remaining chlorinated solvent contamination at the site.**

Documents for GIS Registry

Please revise Figure 3 or the Groundwater Analytical Data Map, March 30, 2009 that was included in the July 22, 2009 *Case Closure Request* prepared by Practical Environmental Consultants, Inc. Remove the contour showing the "approximate extent of vinyl chloride above NR 140 enforcement standards". Also change the label of the contour for the petroleum plume to "approximate extent of petroleum impacts in the groundwater exceeding NR 140 enforcement standards".

A copy of the February 27, 2007 letter written to the Birdell Brellenthin with City of Lake Geneva notifying the City of residual soil and groundwater impacts on the property at 499 West Main Street (site property) was included in the March 20, 2007 *Case Summary and Closeout Request*. The copy of the return receipt/signature confirmation was not included in the March 20, 2007 *Case Summary and Closeout Request*. Please send the Department a copy of the return receipt/signature confirmation. The Department does have a copy of the return receipt/signature confirmation for the July 22, 2009 letter written to the Birdell Brellenthin with City of Lake Geneva notifying the City of residual soil and groundwater impacts on the property east of 499 West Main Street (site property).

When the above conditions have been satisfied, please submit the appropriate documentation (for example, well abandonment forms, disposal receipts, copies of correspondence, etc.) to verify that applicable conditions have been met, and your case will be closed. Please direct correspondence with the site FID# and BRRTS# noted to: Victoria Stovall, Wisconsin Department of Natural Resources, 2300 N. Dr. ML King Dr., Milwaukee, WI 53212.

Your site will be listed on the DNR Remediation and Redevelopment GIS Registry. Information that was submitted with your closure request application will be included on the GIS Registry. To review the site on the GIS Registry web page, visit the RR Sites Map page at: <http://dnr.wi.gov/org/aw/rr/gis/index.htm>.

Section 101.143, Wis. Stats., requires that PECFA claimants seeking reimbursement of interest costs, for sites with petroleum contamination, submit a final reimbursement claim within 120 days after they receive a closure letter on their site. For claims not received by the PECFA Program within 120 days of the date of this letter, interest costs after 60 days of the date of this letter will not be eligible for PECFA reimbursement. If there is equipment purchased with PECFA funds remaining at the site, contact the Commerce PECFA Program to determine the method for salvaging the equipment.

Please be aware that the case may be reopened pursuant to s. NR 726.09, Wis. Adm. Code, if additional information regarding site conditions indicates that contamination on or from the site poses a threat to public health, safety, or welfare or to the environment.

Chlorinated Solvent Contamination

In order to close the chlorinated solvent contamination case it will be necessary to demonstrate that the chlorinated solvent plume in the groundwater is defined and is stable or receding as required under s. NR 726.05(2)(b), Wis. Adm. Code. This can be accomplished by continuing to sample the remaining groundwater monitoring wells (MW-1, MW-4, MW-5 and MW-8) and piezometer PZ-1 at the site for volatile organic compounds (VOCs). You may wish to install an additional groundwater monitoring well downgradient from MW-5 and MW-8 on the adjacent property, but the Department is not requiring it at this time. If the concentrations of chlorinated VOCs continue to increase in MW-8, the Department will require a groundwater monitoring well downgradient from MW-8 to define the extent of the plume. Please provide the Department with a brief groundwater monitoring plan for the chlorinated solvent contamination case.

The Department appreciates the actions you are taking to restore the environment at this site. If you have any questions regarding this letter, please contact me at (262) 574-2166.

Sincerely,



David G. Volkert
Hydrogeologist
Bureau for Remediation & Redevelopment

cc: Holly Jankovic, Practical Environmental Consultants, Inc.
SER File

15-456-01-44
(Doc 2)

SSA # 2067

LIMITED WARRANTY DEED

Document Number

Loc No. 2067

This Deed, made between Speedway SuperAmerica LLC, a Delaware limited liability company, Grantor, whose tax mailing address is 539 South Main Street, Findlay, Ohio 45840 and the City of Lake Geneva, a municipal corporation, Grantee, whose tax mailing address is 361 Main Street, Lake Geneva, Wisconsin 53147.

Grantor, for a valuable consideration, conveys with limited warranty covenants to Grantee the following described real estate in Walworth County, State of Wisconsin, and more particularly described as follows:

SEE EXHIBIT "A" ATTACHED HERETO AND MADE A PART HEREOF.

Property Address: 499 West Main Street, Lake Geneva, WI 53147

Return To:

ZOP 00302

Parcel Identification Number (PIN)
This is not homestead property.

Exceptions to Warranties:

(A) Taxes and assessments (both general and special), not now due and payable; (b) Zoning ordinances, subdivision and planning laws and regulations and building code restrictions and all laws, rules and regulations relating to land and structures and their use, including but not limited to governmental regulations relating to buildings, building construction, building line and use and occupancy restrictions, and violations of any of the foregoing; (c) Easements, conditions, reservations, agreements and restrictions of record, if any; (d) Such a state of facts as an accurate survey might show; and (e) All legal roads and highways.

(B) Grantee agrees that for a period of twenty-five (25) years from and after the date of this conveyance, the premises shall not be used for a convenience store or for the sale, marketing, storage or advertising of petroleum fuels or motor oils, and that this restriction shall be a covenant running with the land and shall be contained in and made a part of every deed, mortgage, lease or other instrument affecting the title to said premises.

(C) This deed is subject to the following reservations, restrictions and conditions which shall be covenants running with the land and shall be binding upon Grantee, its successors, assigns and all future owners of the premises, and their respective directors, officers, employees, contractors, agents, representatives, lessees, licensees, invitees, and any user or occupant of all or any portion of the premises (collectively, "Grantee", for purposes of these reservations, restrictions and conditions):

1. Grantor, its successors and assigns reserves the right to enter upon the premises, at no cost to Grantor, at reasonable times to conduct any Corrective Action only as and when required by the governmental agency with jurisdiction (the "Agency") in connection with a release of petroleum hydrocarbons at the premises. As used herein, the term, "Corrective Action", shall refer to one or more of the following activities: investigation, assessment, monitoring, sampling, analysis, cleanup, removal, disposal, on-site treatment, off-site treatment, active remediation, passive remediation, remediation alternatives including but not limited to risk-based corrective action ("RBCA"), if applicable, and/or other activities approved, concurred in or required by the Agency. In performing any Corrective Action at the premises, Grantor will have the right to rely on and use any current, future or revised or amended state cleanup/remediation standards, guidelines or criteria or revised federal cleanup/remediation standards, if applicable, including without limitation any site-specific risk-based soil and groundwater cleanup objectives or other similar RBCA policies administered by the Agency. In performing any Corrective Action at the premises, Grantor may also rely on and implement institutional controls as provided for in applicable laws, regulations and policies to ensure the protection of public health, safety or welfare and the environment. Grantee acknowledges that such institutional controls may require deed recordation running with the land at the premises. Such deed recordation would contain certain restrictions based on site-specific exposure such as prohibiting the use of groundwater at the premises, requiring that the use of the premises remain commercial/industrial, or requiring the premises, or a portion of the premises, to be paved or that existing pavement remain in place and be properly maintained. Grantee agrees to permit reasonable institutional controls regarding the premises in connection with Grantor's performance of any Corrective Action thereon. Grantee agrees to provide Grantor, at no cost to Grantor, with Grantee's written consent and signature as needed in connection with the preparation, execution and recording of any necessary documents relating to any institutional controls which are to be recorded on the premises as part of Grantor's performance of Corrective Action. Such institutional controls, if necessary, would not prohibit the use of the premises for industrial/commercial purposes. Grantor reserves its legal appeal rights with respect to any orders, directives or requests of the Agency concerning but not limited to Corrective Action at the premises. Grantee agrees that, without prior written approval from Grantor, Grantee will not engage in any activity which would interfere with Grantor's

performance of any Corrective Action at the premises. Such approval shall not be unreasonably withheld by Grantor. In the event that Grantee interferes with Grantor's performance of Corrective Action, Grantee agrees to pay Grantor for the reasonable costs incurred by Grantor as a result of any such interference, including, but not limited to, costs to replace monitoring wells that are damaged or destroyed by Grantee's activities.

2. The use of the premises shall be restricted solely to industrial land uses/utility/commercial/industrial use.

3. The installation and/or existence of potable wells on the premises is prohibited. The groundwater underneath the premises shall not be used for any purpose whatsoever. This restriction, however, does not prohibit the installation or use of any compliance wells, or any groundwater monitoring, recovery or extraction wells or similar devices, used for or related to the performance of any Corrective Action.

4. Grantee shall not have any claim against Grantor, or Grantor's parent companies, affiliates, predecessors, successors, assigns, subsidiary companies or their respective past, present and future officers, employees, agents and/or representatives (collectively, the "Released Parties"), based upon, related to or arising out of the presence of any contamination on, under or at the premises. The Released Parties are hereby forever released from any and all such claims including, but not limited to, any and all claims and statutory causes of action under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA), the Resource Conservation and Recovery Act (RCRA), the Clean Water Act, the state law equivalents of such acts, state and federal underground storage tank laws and regulations and all other environmental laws and regulations, all as amended. This release shall not apply to claims of breach of that certain Offer to Purchase (including Exhibit "B") dated January 30, 2004 between Grantor and Grantee that may arise in the future.

5. Grantee agrees to adhere to, and comply with, the terms of any closure or no further action/remediation letter or determination from the Agency regarding Grantor's performance of Corrective Action.

6. Notwithstanding anything herein to the contrary, Grantee shall not be responsible for any and all existing environmental contamination at the premises, including the migration of said existing environmental contamination which occurs prior to or subsequent to closing.

7. Grantee hereby agrees to defend (with counsel reasonably acceptable to the Released Parties), indemnify and hold the Released Parties (as defined above) harmless from and against any and all liabilities, claims, losses, suits, actions, judgments, damages, costs (including reasonable attorneys' fees) or penalties that result from, arise out of or relate in any way to any violation of the reservations, restrictions and/or conditions contained in this deed.

8. In case any one or more of the reservations, restrictions or conditions (or portions thereof) contained in this deed shall, for any reason, be held to be invalid, illegal or legally unenforceable, in any respect, such invalidity, illegality or unenforceability shall not affect any other portion of that provision or any other provision hereof (whether or not clearly divisible from such provision or portion thereof), and the above reservations, restrictions and conditions shall be construed and interpreted in the manner which is valid, legal and legally enforceable, and which is most nearly consistent with the intention of Grantor and Grantee as evidenced by the above reservations, restrictions and conditions."

Dated this 28th day of ^{April}~~May~~, 2004.

Signed and acknowledged in the presence of:

Vanessa Van Velzor

Print: Vanessa Van Velzor

Boedie B. Lawson

Print: Boedie B. Lawson

SPEEDWAY SUPERAMERICA LLC

BY: J. T. Morgan

Name: J. T. Morgan

Title: Senior Vice President - Operations

STATE OF OHIO)
) SS.
COUNTY OF CLARK)

BEFORE me, a Notary Public in and for said State of Ohio personally appeared the above named SPEEDWAY SUPERAMERICA, LLC, a Delaware limited liability company, by J. T. Morgan, its Senior Vice President - Operations, who acknowledged that he did sign the foregoing instrument and that the same is the free act and deed of said company, and his free act and deed personally and as such officer.

IN TESTIMONY WHEREOF, I have hereunto set my hand and official seal, at Enon, Ohio, this 28 day of April, 2004.

Natalie A. Webster
Notary Public

My Commission Expires:

NATALIE A. WEBSTER, Notary Public
In and for the State of Ohio
My Commission Expires March 28, 2007

This Instrument Prepared by:
Nicole M. Busey, Attorney-at-Law
539 South Main Street
Findlay, Ohio 45840


EXHIBIT "A"

Legal Description

Situated in the City of Lake Geneva, County of Walworth, State of Wisconsin: Commencing at a point in the center line of Main Street in the City of Lake Geneva (formerly Village of Geneva), county and state aforesaid, where the Western line of the Railway now operated by the Chicago & Northwestern Railway Company intersects the center line of Main Street; run thence Northwesterly in the Southwest line of said Railway lands to the center of the outlet of Geneva Lake; thence Southwesterly along the center of said outlet to the center of Main Street; thence East in the center of said Main Street to the place of beginning; excepting the tract described as follows: Commencing at a point in the North line of said Main Street where the Southwesterly line of said Railway Company's right-of-way intersects the said street line; thence Northwesterly in said right-of-way to a point where said right-of-way makes an angle to the Northeast, said last named point being the place of beginning; thence Northwesterly in the line of the right-of-way first mentioned produced or extended, to the center line of White River; the outlet of Geneva Lake; thence Northeasterly in the center line of said White River to the South or Southwest line of the right-of-way of said Railway Company; thence Southeasterly in the line of the right-of-way to a point where the said boundary line of the right-of-way makes a right angle to the Southwest; thence Southwesterly in said right-of-way to the place of beginning.


The above is the description of record and is subject to valid and subsisting easements and restriction of record.

Prior Deed Reference: Vol. 88, Page 191



S.T.H. 50 Main Street (100' R.O.W.)

201.32'



S.T.H. 50

Main Street (100' R.O.W.)

201.32'

STATEMENT BY REPOSIBLE PARTY

Speedway SuperAmerica LLC, the responsible party for the property located at 499 West Main Street, Lake Geneva, Wisconsin, states that the legal description provided to the Wisconsin Department of Natural Resources (and attached to this statement) for case file reference **03-65-192121** is complete and accurate to the best of our knowledge.




Signature of Representative for Responsible Party

03-19-2007

Date

FIGURE 1 - GENERAL SITE LOCATION



© 2002 DeLorme. 3-D TopoQuads®. Data copyright of content owner.
www.delorme.com



TN
★
MN
0.0°E






FIG. 1. MONITORING WELL LOCATIONS

PEC \ 2067_BASE.DWG



PEC \ 2067_BASE.DWG



Practical Environmental Consultants, Inc.				
1305 Remington Road, Suite A Schaumburg, Illinois 60173		Phone 847.519.3430 Fax 847.519.3431		
GROUNDWATER FLOW MAP 2/3/2006		SPEEDWAY STATION #2067 499 WEST MAIN STREET LAKE GENEVA, WISCONSIN		
DATE	SCALE	APPROVED	DWN. BY	FIGURE
2/13/2007	AS SHOWN		KAL	3

Table 1 (continued)
 VOCs
 Soil Analytical Results
 Speedway SuperAmerica #2067
 Lake Geneva, WI

Sample	Sample	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE	1,2,4 Trimethylbenzene	1,3,5 Trimethylbenzene	1,3, Dichloroethane	Gasoline Range Organics	Isopropylbenzene	Lead	Methylene Chloride	Naphthalene	Tetra-Chloroethane	Trichloroethane	Vinyl Chloride	n-Butylbenzene	n-Propylbenzene	p-Isopropyltoluene	sec-Butylbenzene	trans-1,2-Dichloroethane	
Location	Date	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)																	
NR-720 Table 1		0.0055	1.5	2.9	4.1	NA	NA	NA	0.0049	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
NR-746 Table 1		8.5	38	4.6	42	NA	83	11	0.6	NA	NA	NA	NA	2.7	NA	NA	NA	NA	NA	NA	NA	NA	NA
GP-07 (2-4)	08/12/1999	0.990	2.500	1.100	6.700	0.083	2.8	0.78	<0.025	710	0.077	8.8	0.054	0.83	<0.025	<0.025	<0.025	<0.025	0.28	<0.025	0.032	<0.025	<0.025
GP-08 (2-4)	08/12/1999	< 0.025	0.066	< 0.025	0.051	< 0.025	<0.025	<0.025	<0.025	5.2	<0.025	16	0.076	0.13	<0.025	<0.025	<0.025	<0.025	0.041	<0.025	<0.025	<0.025	<0.025
GP-08 (8-10)	08/12/1999	< 0.025	< 0.025	< 0.025	0.039	< 0.025	<0.025	<0.025	<0.025	<2.8	<3.6												
GP-09 (4-6)	04/03/2000	0.150	< 0.025	< 0.025	0.870	< 0.025	0.28	0.096	<0.025		<0.025		<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	0.047	0.23	<0.025	<0.025	<0.025
GP-10 (4-6)	04/03/2000	< 0.025	< 0.025	< 0.025	< 0.050	< 0.025	<0.025	<0.025	<0.025		<0.025		<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025
GP-11 (2-4)	04/03/2000	1.100	4.400	9.500	49.000	< 0.100	22	6.9	<0.1		0.67		<0.1	3.3	<0.1	<0.1	<0.1	<0.1	3.3	0.24	0.34	<0.1	<0.1
GP-12 (2-4)	04/03/2000	0.180	< 0.025	0.029	0.260	< 0.025	0.54	<0.25															
GP-13 (4-6)	04/03/2000	0.043	< 0.025	0.028	0.098	< 0.025	0.5	0.17	<0.025		<0.025		<0.025	0.05	<0.025	<0.025	<0.025	<0.025	0.04	<0.025	<0.025	<0.025	<0.025
GP-14 (2-4)	04/03/2000	1.100	< 0.025	0.250	2.410	0.094	2.2	0.72															
GP-15 (4-6)	04/03/2000	0.030	< 0.025	< 0.025	< 0.050	< 0.025	<0.025	<0.025															
GP-16 (2-4)	04/03/2000	< 0.025	< 0.025	< 0.025	< 0.050	< 0.025	<0.025	<0.025	<0.025		<0.025		<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025
GP-17 (6-8)	04/03/2000	< 0.025	< 0.025	< 0.025	< 0.050	< 0.025	0.052	<0.025	<0.025		<0.025		<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025
GP-18 (4-6)	04/03/2000	< 0.025	< 0.025	< 0.025	< 0.050	< 0.025	<0.025	<0.025	<0.025		<0.025		<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025
GP-19 (2-4)	04/03/2000	< 0.025	< 0.025	< 0.025	< 0.050	< 0.025	<0.025	<0.025	<0.025		<0.025		<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025
GP-20 (2-4)	04/03/2000	< 0.025	< 0.025	< 0.025	< 0.050	< 0.025	<0.025	<0.025	<0.025		<0.025		<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025
MW-04 (12-14)	08/26/1999	< 0.025	< 0.025	< 0.025	< 0.050	< 0.025	<0.025	<0.025		<2.8	6												
MW-04 (2-4)	08/26/1999	< 0.025	< 0.025	< 0.025	< 0.050	< 0.025	<0.025	<0.025		<2.8	6												
MW-8 (3-5)	04/26/2005	< 0.058	< 0.058	< 0.058	< 0.178	< 0.058	<0.058	<0.058	<0.058		<0.058		<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058
MW-8 (7-9)	04/26/2005	< 0.054	< 0.054	< 0.054	< 0.164	< 0.054	<0.058	<0.058	<0.058		<0.058		<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058
MW-9 (3-5)	04/26/2005	< 0.055	< 0.055	< 0.055	< 0.165	< 0.055	<0.058	<0.058	<0.058		<0.058		<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058
MW-9 (7-9)	04/26/2005	< 0.058	< 0.058	< 0.058	< 0.178	< 0.058	<0.058	<0.058	<0.058		<0.058		<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058	<0.058
PZ-1 (11-13)	04/30/2002	< 0.025	< 0.025	< 0.025	< 0.050	< 0.025	<0.025	<0.025	<0.025		<0.025		<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025
PZ-1 (3-5)	04/30/2002	< 0.025	< 0.025	< 0.025	< 0.050	< 0.025	0.043	<0.025	<0.025		<0.025		<0.025	0.071	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025	<0.025

BLANK = NOT SAMPLED

NA = NO ANALYTICAL

ITALICS = ABOVE NR-720 RESIDUAL CONTAMINATION LEVELS

BOLD = ABOVE RR-746 TABLE 1 RESIDUAL PETROLEUM PRODUCT

< = BELOW LABORATORY DETECTION LIMITS

Table 2
VOCs
Groundwater Analytical Results
Speedway SuperAmerica #2067
Lake Geneva, WI

Sample	Reading	TOC	GW Elev	GW Depth	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE	Trimethylbenzenes	Methylene chloride	Napthalene	Tetrachloroethene	trichloroethene	vinyl chloride	cis-dichloroethane	trans-1,2-dichloroethene	lead	
Location	Date	Elev (feet)	(feet)	(feet)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	
Action Levels - NR-140 Enforcement Standards					5	1000	700	10000	60	480	5	40	5	5	0.2	70	100	15	
Action Levels - NR-140 Preventative Action Limits					0.5	200	140	1000	12	96	0.5	8	0.5	0.02	7	20	1.5		
MW-1	09/27/1999	861.53	847.93	13.6	< 0.27	< 0.27	< 0.32	< 0.67	< 0.32	< 0.49	< 0.71	< 0.35	< 0.43	< 0.37	< 0.20	< 0.28	< 0.79	< 4.4	
	12/10/1999	861.53	847.64	13.89	< 0.26	< 0.21	< 0.24	1.1	< 0.22	< 1.4									
	11/01/2000	861.53	848.49	13.04	< 0.29	< 1.1	< 0.57	< 0.63	< 0.2	< 0.63	< 0.36	< 0.27	< 0.65	< 0.32	< 0.19	< 0.27	< 0.35		
	02/05/2001	861.53	849.84	11.89	< 0.29	< 0.13	< 0.57	< 0.63	< 0.2	< 0.63	< 0.36	< 0.27	< 0.65	< 0.32	< 0.19	< 0.27	< 0.35		
	05/17/2001	861.53	849.85	11.68	< 0.45	< 0.68	< 0.82	< 2.47	< 0.43	< 1.86									
	08/08/2001	861.53	848.51	13.02	< 0.45	< 0.68	< 0.82	< 2.47	< 0.43	< 1.86									
	05/09/2002	861.53	849.66	11.87															
	03/25/2003	861.53	848.32	13.21	< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 2.7	< 0.43	< 0.74	< 0.45	< 0.48	< 0.18	< 0.83	< 0.89		
	06/12/2003	861.53	849.72	11.81	< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 2.8	< 0.43	< 0.74	< 0.45	< 0.48	< 0.18	< 0.83	< 0.89		
	09/22/2003	861.53	848.44	13.09	< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 2.8	< 0.43	< 0.74	< 0.45	< 0.48	< 0.18	< 0.83	< 0.89		
	11/18/2003	861.53	848.5	13.03	< 0.3	< 0.58	0.81	1.6	< 0.58	< 1.09									
	03/11/2004	861.53	850.37	11.16	< 1.4	< 2.2	< 1.8	< 8.8	< 2.0	< 6.0	< 1.4	< 2.5	< 1.5	< 1.6	< 0.6	< 2.8	< 3.0		
	05/04/2005	861.53	848.91	12.62	< 0.46	< 1.2	< 1.3	< 3.7	< 1.2	< 1.7									
	02/03/2006	861.53	848.66	12.87	< 0.21	< 0.36	1.2	< 1.1	0.57	< 1.05									
	10/27/2007	861.53	849.27	12.28															
	03/14/2008	861.53	850.13	11.4															
	03/30/2009	861.53	849.82	11.61	< 1.0	< 1.0	< 1.0	< 3.0	< 1.0	< 1.0									
MW-2	09/27/1999	860.88	850.13	10.75	9.8	2.5	4.6	28.51	< 0.32	3.44	< 0.36	6.5	< 0.43	< 0.37	< 0.2	< 0.43	< 0.79		
	12/10/1999	860.88	850.09	10.79	21	< 0.53	7.5	24.0	< 0.55	3.1									
	11/01/2000	860.88	850.30	10.52	14	4.4	9.9	29.05	10.0	5.7									
	02/05/2001	860.88	851.77	9.11	2.5	< 0.38	6.6	14.0	14.0	3.4									
	05/17/2001	860.88	851.56	9.32	10	2.7	20.0	14.37	< 0.2	1.0	< 0.36	0.82	< 0.85	< 0.32	14.37	< 0.27	< 0.35		
	08/08/2001	860.88	850.39	10.49	10	2.9	4.3	16.0	< 0.67	1.77	< 0.85	1.1	< 0.57	< 0.89	< 0.18	< 0.73	< 0.79		
	05/09/2002	860.88	851.18	9.7	12	2.6	8.7	13.0	< 0.67	< 1.34	< 0.65	0.8	< 0.57	< 0.89	< 0.18	< 0.73	< 0.79		
	03/25/2003	860.88	850.28	10.6	9.7	3.0	8.5	17.0	< 0.61	< 2.77	< 0.43	< 0.74	< 0.45	< 0.43	< 0.18	< 0.83	< 0.89		
	06/12/2003	860.88	851.27	9.61	4.2	< 0.67	< 0.54	2.9	< 0.61	< 1.8	< 0.43	< 0.74	< 0.45	< 0.48	< 0.18	< 0.83	< 0.89		
	09/22/2003	860.88	850.21	10.67	11	3.1	0.84	13.0	< 0.61	< 1.8	< 0.43	< 0.74	< 0.45	< 0.48	< 0.18	< 0.83	< 0.19		
	11/18/2003	860.88	850.35	10.52	13	5.7	5.6	28.0	6.3	< 2.46									
	03/11/2004	860.88	851.64	9.24	8.7	2.7	6.6	18.0	< 2.0	< 4.9									
	05/27/2004	860.88	852.41	8.47	10	3.1	8.0	12.0	4.4	1.21									
	05/04/2005	860.88	850.45	10.43	10	3.6	21.0	27.9	15.0	5.5									
	02/03/2006	860.88	850.16	10.72	9.3	3.4	5.7	18.0	4.8	2.2									
	10/27/2007	860.88	850.73	10.15															
	03/14/2008	860.88	851.53	9.35															
	03/30/2009	860.88	851.67	9.21	6.1	2.3	6	12.8	< 1.0	0.91									
MW-3	09/27/1999	861.65	849.5	12.15	17	< 0.27	< 0.32	0.48	1.2	< 0.49	< 0.36	< 0.35	< 0.43	< 0.37	< 0.20	< 0.28	< 0.79	5	
	12/10/1999	861.65	849.49	12.16	11	< 0.21	< 0.24	0.98	0.97	< 1.4									
	11/01/2000	861.65	849.75	11.9	7.6	< 1.1	< 0.57	0.41	1.6	< 0.53	< 0.36	< 0.27	< 0.85	< 0.32	< 0.19	< 0.27	< 0.35		

Table 2 (continued)

VOCs
Groundwater Analytical Results
Speedway SuperAmerica #2067
Lake Geneva, WI

Sample	Reading	TOC	GW Elev	GW Depth	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE	Trimethylbenzenes	Methylene chloride	Naphthalene	Tetrachloroethene	Trichloroethene	Vinyl chloride	cis-dichloroethene	trans-1,2-dichloroethene	lead	
Location	Date	Elev (feet)	(feet)	(feet)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	
Action Levels - NR-140 Enforcement Standards					5	1000	700	10000	60	480	5	40	5	5	0.2	70	100	15	
Action Levels - NR-140 Preventative Action Limits					0.5	200	140	1000	12	96	0.5	8	0.5	0.5	0.02	7	20		1.5
MW-3	02/05/2001	861.65	851	10.65	2.9	< 0.38	< 0.37	4.83	1.4	0.71									
	05/17/2001	861.65	850.93	10.72	3.1	2.3	2.7	5.9	0.53	< 1.86									
	08/08/2001	861.65	849.8	11.85	6.6	< 0.47	< 0.43	< 1.94	< 0.67	< 1.03	< 0.85	< 0.59	< 0.57	< 0.89	< 0.18	< 0.73	< 0.79		
	05/09/2002	861.65	850.55	11.1	5.3	0.87	1.7	4.3	1.6	< 1.86									
	03/25/2003	861.65	849.72	11.93	2	< 0.58	< 0.6	< 1.84	1.6	< 1.18									
	06/12/2003	861.65	850.54	11.11	3.3	0.77	1.9	2.9	0.94	< 1.18									
	09/22/2003	861.65	849.64	12.01	0.98	< 0.58	< 0.6	< 1.84	0.97	< 1.18									
	11/18/2003	861.65	849.77	11.88	9.8	< 0.58	< 0.6	< 1.84	1.7	< 1.18									
	03/11/2004	861.65	851.06	10.59	1.5	< 2.2	< 1.8	< 8.8	< 2.0	< 6.0									
	05/27/2004	861.65	851.93	9.72	5.3	0.48	1.4	< 3.7	1.7	< 2.6									
	05/04/2005	861.65	849.89	11.76	3.3	< 1.2	< 1.3	< 3.7	1.0	< 2.6									
	02/03/2006	861.65	849.96	11.69	6.6	< 0.36	0.64	< 1.54	1.8	< 0.79									
	10/27/2007	861.65	849.96	11.69															
	03/14/2008	861.65	850.35	11.3															
	03/30/2009	861.65	IA	IA															
MW-4	09/27/1999	861.54	850.02	11.52	< 0.27	< 0.27	< 0.32	< 0.67	< 0.32	< 0.49	0.84	< 0.35	4.2	5.5	3.2	57	0.84	< 4.4	
	12/10/1999	861.54	850.01	11.53	< 0.26	< 0.21	< 0.24	< 1.34	< 0.22	< 1.4	< 0.36	< 0.354	2.3	4.1	1.2	34		< 0.79	
	11/01/2000	861.54	850.17	11.37	< 0.29	< 1.1	< 0.57	< 0.63	< 0.2	< 0.53	< 0.36	< 0.27	4	6.5	1.7	54	0.7		
	02/05/2001	861.54	851.19	10.35	< 0.29	< 0.13	< 0.57	< 0.63	< 0.2	< 0.53	0.6	< 0.27	2.9	3.7	7.5	75	0.76		
	02/05/2001	861.54	851.19	10.35															
	05/17/2001	861.54	851.13	10.41	< 0.29	< 0.13	< 0.57	< 0.63	< 0.2	< 0.63	0.47	< 0.27	2.7	4.7	5	60	0.5		
	08/08/2001	861.54	850.19	11.35	< 0.48	< 0.47	< 0.43	< 1.94	< 0.67	< 1.03	< 0.85	< 0.59	1.9	3.8	4.5	38	1.2		
	05/09/2002	861.54	850.8	10.74	< 0.48	< 0.47	< 0.43	< 1.94	< 0.67	< 1.03	< 0.85	< 0.59	4	8.3	7.8	75	< 0.79		
					< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	5.6	10	0.52	53	< 0.89		
	03/25/2003	861.54	850.11	11.43															
	08/12/2003	861.54	850.76	10.78	< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	3.3	3.9	3.3	30	< 0.69		
	09/22/2003	861.54	849.96	11.58	< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	1.5	3	0.55	20	< 0.89		
	11/18/2003	861.54	850.19	11.35	< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	2.8	6.4	0.61	35	< 0.89		
	03/11/2004	861.54	851.25	10.29	< 1.4	< 2.2	< 1.8	< 8.8	< 2.0	< 6.0	< 1.4	< 2.5	6	14	0.75	87	< 3.0		
	05/27/2004	861.54	852.34	9.2	< 1.4	< 2.2	< 1.8	< 8.8	< 2.0	< 6.0	< 1.4	< 2.5	5	9.8	< 0.6	47	< 3.0		
	05/04/2005	861.54	850.23	11.31	< 1.4	< 2.2	< 1.8	< 8.8	< 2.0	< 6.0	< 1.4	< 2.5	2.7	8	0.97	78	1.2		
	02/03/2006	861.54	850.56	10.98	< 0.41	< 0.67	< 1.8	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	< 0.45	16	< 0.18	170	2.3		
	10/27/2007	861.54	850.72	10.82	< 1.4	< 2.2	< 1.8	< 2.63	< 2.0	< 2.8	< 1.4	< 2.5	11	24	14	130	1.3		
	03/14/2008	861.54	851.59	9.95	< 1.0	< 1.0	< 1.0	< 2.63	< 2.0	< 1.0	< 1.4	< 5.0	3.5	5.4	1.2	41.1	< 1.0		
	03/30/2009	861.54	851.45	10.09	< 1.0	< 1.0	< 1.0	< 3.0	< 1.0	< 1.0	< 1.0	< 5.0	31.2	92.7	4.9	290	1.8		
MW-5	09/27/1999	861.67	848.81	12.86	0.97	< 0.27	< 0.32	< 0.67	< 0.32	< 0.49	0.64	< 0.35	< 0.43	< 0.37	12	4.8	< 0.79		
	12/10/1999	861.67	848.77	12.9	1.0	< 0.21	< 0.24	< 1.34	< 0.22	< 1.4	< 0.36	< 0.35	< 0.43	< 0.37	8.7	3.7	< 0.79		
	11/01/2000	861.67	849.19	12.46	2.1	< 1.1	< 0.57	0.63	0.25	< 0.65	< 0.36	< 0.27	< 0.85	< 0.32	23	19	0.38		
	02/05/2001	861.67	850.43	11.24	5.2	0.13	< 0.57	0.91	0.79	< 0.53	< 0.36	< 0.27	< 0.85	< 0.32	< 0.19	< 0.27	< 0.35		
	05/17/2001	861.67	850.46	11.21	3.4	0.17	< 0.57	0.58	< 0.2	< 1.08	0.4	< 0.27	< 0.85	< 0.32	< 0.19	0.38	< 0.35		
	08/08/2001	861.67	849.25	12.42	7.1	0.47	< 0.43	< 1.94	< 0.67	< 1.03	< 0.85	< 0.59	< 0.57	< 0.89	3.9	0.89	< 0.79		
	05/09/2002	861.67	850.06	11.61	9.4	< 0.47	< 0.43	< 1.94	< 0.67	< 1.03	< 0.85	< 0.59	< 0.57	< 0.89	0.71	< 0.73	< 0.79		
	03/05/2003				1.4	< 0.67	< 0.54	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	< 0.45	< 0.48	4.9	6.8	< 0.89		

Table 2 (continued)
 VOCs
 Groundwater Analytical Results
 Speedway SuperAmerica #2067
 Lake Geneva, WI

Sample	Reading	TOC	GW Elev	GW Depth	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE	Trimethylbenzenes	Methylene chloride	Napthalene	Tetrachloroethene	trichloroethene	vinyl chloride	cis-dichloroethane	trans-1,2-dichloroethane	lead
Location	Date	Elev (feet)	(feet)	(feet)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
Action Levels - NR-140 Enforcement Standards					5	1000	700	10000	60	480	5	40	5	5	0.2	70	100	15
Action Levels - NR-140 Preventative Action Limits					0.5	200	140	1000	12	96	0.5	8	0.5	0.5	0.02	7	20	1.5
MW-7	02/03/2006	861.73	IA	IA														
	10/27/2007	861.73	849.88	11.85														
	03/14/2008	861.73	850.38	11.35														
	03/30/2009	861.73	850.55	11.18	< 1.0	< 1.0	< 1.0	< 3.0	< 1.0	< 1.0								
MW-8	05/04/2005	861.23	849.34	11.89	< 1.4	< 2.2	< 1.8	< 6.8	< 2.0	< 6.0	< 1.4	< 2.5	1.3	8.2	8	97	< 0.63	
	02/03/2006	861.23	849.49	11.74	< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	7	4.6	3.2	44	< 0.89	
	10/27/2007	861.23	849.88	11.35	< 1.4	< 2.2	< 1.8	< 2.63	< 2.0	< 2.8	< 1.4	< 2.5	4.8	24	3.5	85	1.2	
	03/14/2008	861.23	850.74	10.49	< 1.0	< 1.0	< 1.0	< 2.83	< 2.0	< 1.0	< 1.4	< 5.0	3.8	11.7	1.4	63.9	1.1	
	03/30/2009	861.23	850.53	10.7	< 1.0	< 1.0	< 1.0	< 3.0	< 1.0	< 1.0	< 1.0	< 5.0	6.3	25.2	< 1.0	166	< 1.0	
MW-9	05/04/2005	861.79	848.92	12.87	< 1.4	< 2.2	< 1.8	< 8.8	< 2.0	< 6.0	< 1.4	< 2.5	< 1.5	< 1.6	< 0.6	< 2.8	< 3.0	
	02/03/2006	861.79	848.82	12.97	< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	< 0.45	< 0.48	< 0.18	2	< 0.89	
	10/27/2007	861.79	849.74	12.05	0.73	< 2.2	< 1.8	< 2.63	< 2.0	< 2.8	< 1.4	< 2.5	< 1.5	< 1.6	< 0.6	< 2.8	< 3.0	
	03/14/2008	861.79	850.59	11.2	< 1.0	< 1.0	< 1.0	< 2.63	< 2.0	< 1.0	< 1.4	< 5.0	< 1.0	< 1.0	< 0.6	< 1.0	< 1.0	
	03/30/2009	861.79	850.02	11.77	< 1.0	< 1.0	< 1.0	< 3.0	< 1.0	< 1.0	< 1.0	< 5.0	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0	
PZ-1	02/09/2002	861.37	857.04	4.33	< 0.48	< 0.47	< 0.43	< 1.94	< 0.67	< 1.03	< 0.85	< 0.59	< 0.57	< 0.69	< 0.18	< 0.73	< 0.79	
	03/25/2003	861.37	854.78	6.59	< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	< 0.45	< 0.48	< 0.18	< 0.83	< 0.89	
	06/12/2003	861.37	855.76	5.61	< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	< 0.45	< 0.48	< 0.18	< 0.83	< 0.89	
	09/22/2003	861.37	853.86	7.51	0.59	< 0.67	< 0.54	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	< 0.45	< 0.48	< 0.18	< 0.83	< 0.89	
	11/18/2003	861.37	854.75	6.62	< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	< 0.45	< 0.48	< 0.18	< 0.83	< 0.89	
	03/11/2004	861.37	854.56	6.81														
	05/04/2005	861.37	855.43	5.94														
	02/03/2006	861.37	854.14	7.23	< 0.41	< 0.67	< 0.54	< 2.63	< 0.61	< 1.8	< 0.43	< 0.74	< 0.45	< 0.48	< 0.18	< 0.83	< 0.89	
	10/27/2007	861.37	855.59	4.78	< 1.4	< 2.2	< 1.8	< 2.63	< 2.0	< 2.8	< 1.4	< 2.5	< 1.5	< 1.6	< 0.6	< 2.8	< 3.0	
	03/14/2008	861.37	858.77	2.6	< 1.0	< 1.0	< 1.0	< 2.63	< 2.0	< 1.0	< 1.4	< 5.0	< 1.0	< 1.0	< 0.6	< 1.0	< 1.0	
	03/30/2009	861.37	860.2	1.17	< 1.0	< 1.0	< 1.0	< 3.0	< 1.0	< 1.0	< 1.0	< 5.0	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0	

BLANK - NOT ANALYZED
 NA - NO ACTION LEVEL
 BOLD - EXCEEDS NR 140 ENFORCEMENT STANDARDS
 ITALICS - EXCEEDS NR 140 PAL ENFORCEMENT STANDARDS
 ug/L - MICROGRAMS PER LITER
 < - BELOW
 < = BEL DETECTION LIMIT
 IA - INACCESSIBLE



Speedway SuperAmerica LLC

P.O. Box 1500
Springfield, OH 45501
Telephone 937-864-3000

February 27, 2007

Birdell J. Brellenthin, President
Department of Public Works and Utilities
City of Lake Geneva
361 West Main Street
Lake Geneva, Wisconsin 53147

RE: Notice of Residual Petroleum Impacts
Former Speedway SuperAmerica #2067
499 West Main Street
Lake Geneva, Wisconsin 53147

Dear Birdell Brellenthin;

Speedway SuperAmerica, LLC (SSA), has prepared this letter to notify you of residual soil and groundwater contamination on your property located at 499 West Main Street in Lake Geneva, Wisconsin. Our environmental consultant (Practical Environmental Consultants, Inc.) has requested closure from the Wisconsin Department of Natural Resources for Speedway SuperAmerica #2067.

The levels of benzene, toluene, ethylbenzene, xylene (BTEX), and methyl tertiary butyl ether (MTBE) contamination in the soil and groundwater on your property are above the state groundwater and soil enforcement standards found in chapter NR 140 and NR-746, Wisconsin Administrative Code. The impacted areas are shown on enclosed Figures 1 and 2. However, the environmental consultants who have investigated this contamination have informed me that this groundwater contamination plume is stable or receding and will naturally degrade over time. Natural attenuation is described in the enclosed Fact Sheet from the Wisconsin Department of Natural Resources (WDNR). SSA believes that allowing natural attenuation to complete the cleanup at this site will meet the requirements for case closure found in NR 726 and chapter NR 746, Wisconsin Administrative Code. Accordingly, SSA will be requesting that the WDNR accept natural attenuation as the final remedy for this site and grant case closure. Closure means that the department will not be requiring any further investigation and cleanup action to be taken, other than the reliance of natural attenuation.

The WDNR will not review SSA's closure request for at least 30 days after the date of this letter. As an affected property owner, you have a right to contact the Department to provide any technical information that you may have that indicated that closure should not be granted for this site. If you would like to submit any information to the WDNR that is relevant to this closure request, you should mail that information to Dave Volkert, Wisconsin Department of Natural Resources, 141 NW Barrow Street Room 180, Waukesha, Wisconsin 53188.


If this case is closed, all properties within the site boundaries where groundwater contamination exceeds chapter NR 140 groundwater enforcement standards will be listed on the Wisconsin Department of Natural Resources' geographic information system (GIS) Registry of Closed Remediation Sites. The information on the GIS registry includes maps showing the location of properties where groundwater contamination above NR 140 enforcement standards was found at the time that the case was closed. This GIS Registry will be available to the general public on the Department of Natural Resources' internet web site. Please review the enclosed legal description of your property, and notify me within next 30 days if the legal description is incorrect.

Should you or any subsequent property owner wish to construct or reconstruct a well on your property, special well construction standards may be necessary to protect the well from the residual groundwater contamination. Any well driller who proposes to construct a well on your property in the future will first need to call the Diggers Hotline (1-800-242-8511) if you property is located outside of the service of a municipally owned water system, or contact the Drinking Water program within the Department of Natural Resources if your property is located within the designated service area of a municipally owned water system, to determine whether there is a need for special well construction standards.

Once the Department makes a decision on our closure request, it will be documented in a letter. If the department grants closure, you may obtain a copy of this letter by requesting a copy from me, by writing the to the agency address given above or by accessing the DNR GIS Registry of Closed Remediation Sites on the internet at www.dnr.state.wi.us/org/at/et/geo/gwur. A copy of the closure letter is included as part of the site file on the GIS Registry of Closed Remediation Sites.

If you need more information, you may contact me, Toby A. Rickabaugh, at (937) 863-6513 or you may contact the Wisconsin Department of Natural Resources project manager Dave Volkert at (262) 574-2166.

Sincerely,
Speedway SuperAmerica LLC



Toby A. Rickabaugh
Environmental Representative

Enclosures

Groundwater Quality Map
Soil Quality Map
Property Deed for 499 West Main Street, Lake Geneva, Wisconsin
RR-671

cc: Andrew Stelk, PEC



LAKE GENEVA UTILITY COMMISSION

Daniel S. Winkler, P.E.
Director of Public Works & Utilities



Birdell Brellenthin
Utility Commission President

Kent Wiedenhoft
Water Superintendent

Scott Tesmer
Wastewater Superintendent

361 Main Street • P.O. Box 187 • Lake Geneva, WI 53147 • Phone (262) 248-2311 • Fax (262) 248-0589

October 22, 2009

Practical Environmental Consultants, Inc.
1305 Remington Road Suite A
Schaumburg, IL 60173
Attn. Ms. Holly Jankovic

RECEIVED
PEC
DATE OCT 24 2009

**Subject: Former Speedway SuperAmerica LLC. Store No. 2067, 499 West Main Street,
Lake Geneva, WI, BRRTS# 03-65-192121, Commerce #53147-1980-99-A,
Request for Certification of Correspondence from the Utility Commission**

Dear Ms. Jankovic:

As requested, please consider this letter as certification that the attached information sent you previously did come from the Lake Geneva Utility Commission files. Attachments herein include a February 27, 2007 Speedway letter (2 pages – Notice of Residual Petroleum Impacts) with ten (10) pages of attached information, and a WDNR letter dated July 26, 2007 (2 pages – Closure Request for Speedway, SuperAmerica Store #2067).

If you have any questions or need any additional certifications or information we may have in our files, please call.

Sincerely,

Daniel S. Winkler, P.E.
Director of Public Works & Utilities

Cc: Burly Brellenthin
Cindy Borkhuis
File

